

COPIES RECEIVED	2
TRIBUTION	
FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

MAR 3 1975

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4042
7. Unit Agreement Name
8. Farm or Lease Name State "DF"
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat Wc
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS **O. C. C.**
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT INTERVAL. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-
2. Name of Operator Yates Petroleum Corporation
3. Address of Operator 207 South 4th Street-Artesia, NM 88210
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>17S</u> RANGE <u>24E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3734' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well is non commercial in the Morrow. Propose to abandon the Morrow by setting CIBP at 7850' and abandon. Abandon the Cisco formation by setting CIBP at 6550', then perforate and treat the ~~WC~~ ^{WC} formation at 4926-4971' for production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie L. Inalafant TITLE Engineer DATE 2-28-75

APPROVED BY W. A. Gussert TITLE SUPERVISOR, DISTRICT II DATE MAR 5 1975

CONDITIONS OF APPROVAL, IF ANY: 30' of cement on top of each BP