

S. P. YATES President Martin Yates, III Vice President John A. Yates Vice President B. W. Harper Sec. Treas.

YATES BUILDING - 207 SOUTH 4TH ST. ARTESIA, NEW MEXICO-88210

September 28, 1977

Mr. Bill Gressett, District Supervisor N.M. Oil Conservation Commission Drawer DD Artesia, New Mexico 88210

> RE: State DF ±1, K4-42, D-35-17S-24E

Dear Bill,

On October 30, 1963, Max Wilson's Geologist picked the top of the Wolfcamp in subject well at 492C'. In our completion report of April 18, 1974 we showed the top of the Wolfcamp at 4920'. However, since February 28, 1975, we have mistakenly called perforations 4926-4971' "Basal Abo". We want to correct this mis-nomer now. A new C-102 is attached hereto designating 320 acres, northhalf of Section 35.

Thank you.

Sincerely,

YATES PETROLEUM CORPORATION

Eddie M. Mahfood Engineer

EMM/pt encl.

KIBENVED

007 8 1977

C. C. C.