

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TP
(Other instruct
verse side)ICATE*
of re-Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

N/M 01171-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> WIW	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Mobil Oil Corporation	8. FARM OR LEASE NAME West Henshaw Premier Unit Tract 7-A
3. ADDRESS OF OPERATOR Three Greenway Plaza East, Suite 600, Houston, Texas 77046	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT Henshaw Crayburg West
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
12. COUNTY OR PARISH Eddy	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

WEST HENSHAW UT #7-A-1 WIW

West Henshaw Fld, Eddy Co., NM

8/17/76 2840 TD, 2813 PBD, SA 2789-2793. Prep MI DA&S Unit.

8/18/76 2840 TD, 2813 PBD, SA 2789-2793. MIRUDA&S Well Serv 8/17/76, POH w/Clrk tbg, left part of pkr in hole, WIH w/EZ-Drill pkr on tbg to 2732, SDFN.

8/19/76 2840 TD, 2813 PBD, SA 2789-2793. Attempt to set EZ-Drill @ 2732, failed, POH, change setting tool, WIH & set @ 2732, PU 500 on annulus/ok, test tbg 3500/ok, Howco sqz SA perfs 2789-2793 w/70x P, TP 2500, spot 6x on ret, circ 10# mud laden br, POH, instl hydraulic jacks, SDFN.

8/20/76 2840 TD, 2813 PBD, SA 2789-2793. Shot 5½ @ 720, pulled 15', hung up, shot @ 379, P & LD 11 jts 5½ 14# K55, spot 40x 250-443, 20x 0-60, SDFN.

8/21/76 2840 TD. Tag plug @ 10', cmt to surf, weld on plate, instl monument, rel DA&S unit 8/20/76, P&A 8/20/76.

FINAL REPORT

RECEIVED
DEC 13 1976
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Authorized Agent

DATE 12-6-76

(This space for Federal or State office use)

APPROVED BY

TITLE

ACTING DISTRICT ENGINEER

DATE

JUL 6 - 1979

CONDITIONS OF APPROVAL, IF ANY: