

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TR - CATE*
(Other instructi on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-063928 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Henshaw Deep Unit

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Henshaw-Wolfcamp

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 14, T-16-S, R-30-E,
NMPM

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Shell Oil Company ✓

3. ADDRESS OF OPERATOR

P. O. Box 1858, Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL & 660' FEL (NE/4, NE/4), Section 14, T-16-S,
R-30-E, NMPM Survey, Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3860' df

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

Plug

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

We propose to spot the following plugs:

TD - 25 sx Incor
9100'-8700' - 75 sx Incor
7800'-7700' - 25 sx Incor
6500'-6400' - 25 sx Incor
4550'-4450' - 25 sx Incor
3100'-3000' - 25 sx Incor
On casing stub - 25 sx Incor
At base of salt (1500'-1400') - 25 sx Incor, only if casing is cut below 2290'
550'- 450' - 25 sx Incor
Surface - 10 sx Incor

RECEIVED

AUG 27 1964

O. C. C.
ARTESIA, OFFICE

Verbally approved by Mr. Shook of U.S.G.S. via telephone conversation with
Mr. Vassar, Shell Oil Company, August 24, 1964.

18. I hereby certify that the foregoing is true and correct

SIGNED

R. E. Christensen

(This space for Federal or State office use)

Acting Division

TITLE Mechanical Engineer

DATE August 25, 1964

APPROVED

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

AUG 26 1964
Ronnie E. Shook
RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.