

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Form Approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

FM-01171-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

F.R. Pass Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

West Lenchaw Grayburg

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 3, T 16-S, R 30-S

12. COUNTY OR PARISH

Eddy

13. STATE

NM

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Finney, Cahoon

3. ADDRESS OF OPERATOR

522 Bldg. of Southwest Midland, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

Unit F 2310' FNL-1650' FWL Sec. 3, TW-16-S, R 30 E  
Eddy County N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3882 CI

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well Plugged & Abandoned as follows;

7-15-74

Set C.I. Bridge plug @ 2705' w/ 35 sx cement on top of plug from 2705' to 2670'

Recovered csg @ 1743, ran tbg to 1743', spotted a 35 sx plug from 1743' to 1621'

Set 50 sx cement plug from 1270' to 1096'

Set 50 sx cement plug from 450' to 322'

Set 50 sx cement plug from 10' to surface

Installed dry hole marker.

Note: All plugs set thru tubing, hole was displaced with, and all plugs displaced w/ salt water brine mud.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE

7-23-74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side