

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN DUPLICATE*
(Other instructions on re-
verse side)Form approved
Budget Bureau No. 22 R1421

Copy to S.F.

5. LEASE DESIGNATION AND SERIAL NO.

LC-067849

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

MALCO "P" Federal

9. WELL NO.

10. FIELD AND POOL, OR WELL AT

REDLAKE (GSA)

11. SEC., T., R., OR BLK. AND
SURVEY OR AREA

34-17-27 NMPM

12. COUNTY OR PARISH

EDDY

13. STATE
N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1987.43 FSL x 1972.58 FWL Sec 34 (Unit K, NE 1/4 SW 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3571 R. D. B.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Limited production and sw disposal expense makes
well uneconomical to produce. Propose to P+ A as follows:
Load hole w/ mud. Spot 30 sx plug (cement) 2160 - 1850'; 25sx.
1625 - 1350'; Out + pull 4 1/2" from appx 1200'. Spot
25 sx. In + out of 4 1/2" stub; 25 sx. In + out of 8 7/8" CSA 1010;
10 sx @ surface and erect P+ A marker.
Make Final cleanup and restore ground to contour.

T-QUEEN 853'

T SAN AND 1552'

RECEIVED

MAR-31969

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

TD- 3200'

9 5/8" CSA 1010' Circ.

PBD- 2890'

4 1/2" SSA 3200 - 4255x.

O. O. O.
ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

FEB 27 1969

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side