

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN 7
(Other instru
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Tenneco Oil Company		8. FARM OR LEASE NAME Etz "B"	
3. ADDRESS OF OPERATOR c/o Hobbs Pipe & Supply Company, Box 2010, Hobbs, N. M.		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 660' FEL		10. FIELD AND POOL, OR WILDCAT Henshaw-Wolfcamp	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)	
		12. COUNTY OR PARISH Eddy	
		13. STATE N. M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Spotted a 25 sx cement plug at 8800'.
2. Spotted a 25 sx cement plug at 4-1/2 casing stub at 7550'.
3. Spotted a 25 sx cement plug at 5810'-5710'.
4. Spotted a 25 sx cement plug at 4520'-4420'.
5. Spotted a 50 sx cement plug at 8-5/8" casing shoe at 3185'.
6. Spotted a 25 sx cement plug at 8-5/8" casing stub at 1000'.
7. Spotted a 25 sx cement plug at 11-3/4 casing shoe at 499'.
8. Spotted a 10 sx cement plug at surface with marker.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]TITLE AgentDATE 2/26/71

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side