GEOLOGICAL SURVEY South Central Region Roswell District			
	.1 District Drawer 1857		
STALLWORTH OH & ROSWell, N	New Mexico 88201		
STATT A CHERRY	DATE 4/3/81		
Operator:	Lease No. LC 029424		
Stallworth Oil Fas me	Well No. 5-ETZ		
8.0, Box 479	Location 10FSL 4 2630' FEL		
Dallas Texas 15221	Sec. 25 T. 165 R. 30E		

The Notice of Intention to Abandon (form 9-331) for the above well has been received, and your proposed down-hole plugging program is hereby approved subject to the following conditions:

See attached program.

Please notify this office in sufficient time so that a representative may witness the plugging of the well.

A notice of your abandonment proposal has been furnished to the Surface Management Agency and, as soon as surface restoration requirements are received, your approved copy of the Notice of Intention to Abandon will be forwarded to you.

Sincerely yours, Peter W Chester

RECEIVED

James A. Gillham District Supervisor

APR 1 3 1981

O. C. D. ARTESIA, OFFICE

DEPARTM	Dodzet Butebu No. 42 R1424. 5. LEANE DESIGNATION AND SERIAL NO. 1.0029424			
SUNDRY NOTIO (Do not use this form for proposal Use "APPLICAT	LES AND REPORTS (ls to drill or to deepen or plug b ION FOR PERMIT-" for such p	DN WELLS mark to a different reservoir.	6 18 18 18 AT (-119 F)	el telet Name
1	······································	Into	7. UNIT AGLEEMENT NAM	E
OIL GAS OTHER X	Injection Well	MSTR	8. FARM OR LEASE NAME	····-· · •
Stallworth Oil & Gas	s, Inc.	MASS	Etz	
3. ADDELSS OF OPERATOR		P2	9. WELL NO.	
P.O. Box 479, Dallas 4. LIGATION OF WELL (Report location cless See also space 17 below.)	arly and in accordance with any	State requirements.	Guare Lake	WILDCAT
At surface 10' FSL & 2630' FEL	. Section 25. T-	16-S, R-30-E	11. SEC., T., B., M., OR HLE	S. AND
10 1511 4 2050 1515			SURVET OR AREA 25, 165, 301	Ξ
14. PERMIT NO.			12. COUNTY OR PARISH 13. STATE	
	3790' G	R	Eddy N	New Mexic
16. Check App	propriate Box To Indicate N	lature of Notice, Report, or C	Other Data	
NOTICE OF INTENT	10N TO:	STBSEQ	TENT REPORT OF:	
	TLL OR ALTER CASING	WATER SHUT-OFF	ALTERING CASE	
	CLTIPLE COMPLETE XX	SHOOTING OR ACIDIZING	ABANDONMENT	[]
	HANGE PLANS	(Other)	of multiple completion on	Well
(Other)		I Completion or Recomp	letion Report and Log form.	.)
 DESCRIBE PROPOSED OR COMPLETED OPER. proposed work. If well is direction nent to this work.) 	ally drilled, give subsurface local	tions and measured and true vertic	al depths for all markers a	nd zones perti-
Administrative appro Oil & Gas, Inc. No. Square Lake (Graybu	5 Ada Nye Etz w	aterflood injectio	on well, in th	orth ne
This well was origin lease for the purpo of the Premier and capacity since init	se of injecting [.] Lovington Horizo	water in a coopera ns and has function	ative waterflo oned in that	z pod
proceed to plug and	ay interval from stuck and it is advise us of you abandon this we	annular injection extremely doubtfu r recommendations ll.	n through the l that it can so that we ma RFC	be
see avacher Contact a	tesia, n. m.	U.S.G.S. OFF	ce APR1	3 19 81
See attached Contact & 74 hrs. befo	re starting	y work.	Ö. Č Artesia	
18. I hereby certify that the foresolds is		. Vice President	March	20, 1981
SIGNED			DATE	
APPROVED BY DECONDITIONS OF APPROVAL, 419 AN	1 Choster			

JAMES A. GILLHAM DISTRICT SUPERVIS**®See Instructions on Reverse Side**

Digth 10 sock cement plug at surface. Perforate 5'2" caring at 625' Squeepe 50 sucher comment across top of salt. Sport 10 sucke plug, invide 5'2" caring, across the perft. 5% asing 600 top of falt 2 % tubbing stuck Separate tubling above freepoint. Spot 100' CARTET, TOC cement across stub. 1659' Base of balt 23" Tubbing - Perft, 2964 - 3045' - 3087 packer - Perft 3152-63' Squarge perfo below packer through inj. Tubbing.

Flugging program for:

Stallworth Oil + Yay Inc. #5 ETZ, 10'FSLY 2630' FEC Sec 25, T 165, A 30E JEANERO. LC 029424