

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN THE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC-063933

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ 2. NAME OF OPERATOR Shell Oil Company (Western Division) 3. ADDRESS OF OPERATOR P. O. Box 1509, Midland, Texas 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 600' FWL (SW/4 NW/4), Section 25, T-16-S, R-30-E, NMPM Survey, Eddy County, New Mexico 14. PERMIT NO.	7. UNIT AGREEMENT NAME Unit 8. FARM OR LEASE NAME Henshaw Deep Unit 9. WELL NO. 15 10. FIELD AND POOL, OR WILDCAT Henshaw-Wolfcamp 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25, T-16-S, R-30-E NMPM 12. COUNTY Eddy 13. STATE New Mexico
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3846' DF	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) Plug Back ☒	

(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

February 10, 1967 thru February 14, 1967.

1. Spotted 25 sx cement plug 8802' - 8830' (Wolfcamp Perforations)
2. Shot & pulled 6995' of 4 1/2" casing.
3. Spotted the following cement plugs:

50 sx at 6995' (top of 4 1/2" casing stub)
25 sx at 6550'
50 sx at 3450'

4. Completed plugging back to San Andres February 14, 1967.
The remainder of well sold to The Ryder Scott Company of Wichita Falls, Texas, for use as water injection well for The Lovington Sand Waterflood.

RECEIVED

**RECEIVED
FEB 23 1967
GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO**

18. I hereby certify that the foregoing is true and correct

Original Signed By R. J. Doubek TITLE Division Mechanical Engineer DATE February 20, 1967

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

APPROVED
FEB 24
R. L. BECKMAN
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection pending to approval of the abandonment.