February 5, 1968

Ryder Scott Management Company 922 8th Street Wichita Falls, Texas 76301

> Re: Etz A Federal Well No. 1 E 25-16-30, Square Lake Pool, Eddy County, New Mexico

Gentlemen:

As the subject well is not directly or diagonally offset by an injection well, it is not a part of the Loe flood project area and should not be shown on Form C-120, Monthly Injection Report.

We have corrected reports now in our files. Please make this change before filing future waterflood reports.

Very truly yours,

OIL CONSERVATION COMMISSION

R. L. Stamets Geologist

RLS/bh

Felling comparison

నారిగా విజాదంగి గొరుగా రాజాయార్ **చితాగుతు**ర్ర ప్రేశ్ గార్ ఆర్ స్ గాంక్రమ విజర్తు ప్రాణంత్ పెట్టర్

"⊕: brack beiderel bell da, t.c. 20+10+001, kaste Loka Muste 2085 Naaryk ke Voolan

is the second with a crochlade line (2000) or fixed as the second of the

se have controlled toporte now in our files. Ateact maxes the limite herote filitar subare saterficed separts.

and where the states

STELLOWERSKEEPING CONNECTOR

an 200 D**€8486**53 Certificant Certificant