

N. M. O. C. C. COPY
(SUBMIT IN TRIPPLICATE)

Budget Bureau No. 42-2284
Approval expires 12-31-66

Land Office Las Cruces

Lease No. 068064

Unit K B

RECEIVED

DEC 21 1966

SUNDR NOTICES AND REPORTS ON WELLS

ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL
NOTICE OF INTENTION TO CHANGE
NOTICE OF INTENTION TO TEST
NOTICE OF INTENTION TO RE-DRILL
NOTICE OF INTENTION TO SHOOT
NOTICE OF INTENTION TO PULL
NOTICE OF INTENTION TO ABANDON

ANS	SUBSEQUENT REPORT OF WATER SHUT-OFF	
R SHUT-OFF	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
R REPAIR WELL	SUBSEQUENT REPORT OF ALTERING CASING	
ACIDIZE	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
PER CASING	SUBSEQUENT REPORT OF ABANDONMENT	
WELL	SUPPLEMENTARY WELL HISTORY	
	perforate & acidize	X

(WH)

SEE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA

Grien Fe
Well No. 15 is located
NW₄ NW₄ NE₄
(1/4 Sec. and 1/4 Sec. No.)
Square Lake
(Field)

December 19, 1966
2630
d 10 ft. from [N] line and 2360 ft. from [E] line of sec. 31
16 31 N.M.P.M.
(Twp.) (Range) (Meridian)
Eddy New Mexico
(County or Subdivision) (State or Territory)

The elevation of the derrick

floor above sea level is 3844' ft.

DETAILS OF WORK

(State names of and expected depth)

Objective sands; show class, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work

Confirming telephone conversation on December 19, 1966. Verbal permission was obtained to complete this well for water injection. On the above date the 5 1/2" casing was perforated w/4" NCF II gun 1 hole per ft at 3289 1/2, 3288 1/2, 3287 1/2, 3286 1/2, 3285 1/2, 3284 1/2, 3283 1/2, 3282 1/2, 3281 1/2, 3280 1/2, 3161, 3160, 3159, 3158, 3157, 3116, 3115, 3114, 3113, 3112. A 5 1/2" bridge plug & 5 1/2" RTTS packer were run on 2 3/8" tubing and perforations were treated with 15% HCl acid.

conversation on December 19, 1966. Verbal permission was obtained to complete this well for water injection. On the above date the 5 1/2" casing was perforated w/4" NCF II gun 1 hole per ft at 3289 1/2, 3288 1/2, 3287 1/2, 3286 1/2, 3285 1/2, 3284 1/2, 3283 1/2, 3282 1/2, 3281 1/2, 3280 1/2, 3161, 3160, 3159, 3158, 3157, 3116, 3115, 3114, 3113, 3112. A 5 1/2" bridge plug & 5 1/2" RTTS packer were run on 2 3/8" tubing and perforations were treated with 15% HCl acid.

I understand that this plan of

must receive approval in writing by the Geological Survey before operations may be commenced.

Company Anadarko

Production Company, Agent for (Western Oil Fields, Inc)

Address P. O. Box

60

Artesia,

N.M.

By Chandler Haggard

Title Production Foreman