

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
OG 2284

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry Hole	7. Unit Agreement Name
2. Name of Operator Charles C. Loveless, Jr.	8. Farm or Lease Name Marathon-State
3. Address of Operator P. O. Box 566, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER C , 660 FEET FROM THE North LINE AND 2180 FEET FROM THE West LINE, SECTION 4 TOWNSHIP 17S RANGE 26E NMPM.	10. Field and Pool, or Wildcat Wildcat (ing)
15. Elevation (Show whether DF, RT, GR, etc.) 3365 DF	12. Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

With 1228 feet 8 5/8-inch casing cemented to top remaining in hole and a TD 6871 the following cement plugs were set:

50 sx at TD
25 sx at 6460
25 sx at 5000
25 sx at 3500
25 sx at 1850 - 1950
25 sx at 1150 - 1275
25 sx at 500

Cement plug in pipe at surface and dry hole marker installed.

RECEIVED

JUL 15 1966

**O. C. C.
ARTEBIA, OFFICE**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Charles C. Loveless, Jr.* TITLE Operator DATE 7-14-66

APPROVED BY *W. A. Gussert* TITLE OIL AND GAS INSPECTION DATE JUL 18 1966

CONDITIONS OF APPROVAL, IF ANY: