

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>P &amp; A</b> <b>AUG 24 1966</b>		7. Unit Agreement Name
2. Name of Operator <b>Atlantic Richfield Company</b>		8. Farm or Lease Name <b>H. W. Hornbaker</b>
3. Address of Operator <b>P. O. Box 1978, Roswell, New Mexico</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>O</b> <b>510</b> FEET FROM THE <b>South</b> LINE AND <b>1680</b> FEET FROM THE <b>East</b> LINE, SECTION <b>20</b> TOWNSHIP <b>17-S</b> RANGE <b>26-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Wildcat-Morrow</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3402' DF</b>		12. County <b>Eddy</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled a 7-7/8" hole to a T.D. of 8755' without encountering commercial hydrocarbons. This well was plugged and abandoned by setting the following neat Incor cement plugs:

30 sx from 8375-8475  
30 sx from 6475-6575  
30 sx from 5450-5550  
30 sx from 4225-4325

30 sx from 2250-2350  
40 sx from 1375-1475  
30 sx from 500-600  
10 sx in top of well

9.1#/gal mud was used to spot all plugs. 8-5/8" surface casing was left intact. A dry hole marker was erected. We will notify your office by letter when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed

A. D. Kloxin

SIGNED

TITLE **Dist. Drlg. & Prod. Supt.** DATE **8-23-66**

APPROVED BY

TITLE **OIL AND GAS INSPECTOR**

DATE **DEC 5 1966**

CONDITIONS OF APPROVAL, IF ANY: