	DEPARTMENT					Form C-103					
	O. OF COPIES RECEIVED OIL CONSERVATION DIVISION RECEIVED			RECEIVED		Revised 10-1-78					
DISTRIBUTION		P.O. Box		"TOLIVED	le						
SANTA FE		SANTA FE, NEW	_	DD 1 5 4000	5a. Indicate						
FILE U.S.G.S			A	PR 1 5 1983	State X	Fee —					
LAND OFFICE				~ ~ ~	5 State OII	& Gas Lease No.					
OPERATOR				O. C. D.	3. 31416 011	a oas Lease NO.					
			AR	TESIA, OFFICE	06-4	5016					
SUNDRY NOTICES AND REPORTS ON WELLS						×××××××××××××××××××××××××××××××××××××××					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT					XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX						
RESERVOIR, USE MAPPLICATION FOR PERMIT-M (FORM C-1011 FOR SUCH PROPOSALS,)					XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX						
. OIL GAS					7. Unit Agreement Name						
WELL	WELL X	OTHER] .	_					
2. Name of Operator					8. Farm or Lease Name						
Read & Stevens, Inc. V					Bogle Flats						
3. Address of Operator					9. Well No.						
P.O. Box 1518, Roswell, NM 88201						1					
4. Location of Well				10. Field and	Pool, or Wildcat						
UNIT LETTER N . 990 FEET FROM THE South LINE AND 1650 FEET FROM				Mesa Queen XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX							
THE West LINE. SECTION 12 TOWNSHIP 16S RANGE 31E NMPM				XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX							
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX				12. County	XXXXXXXXXXXXXXXXX						
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX					Eddy	XXXXXXXXXXXXXXXXX					
		ate Box To Indicate N	ature of Notic	•							
NOT	TICE OF INTENTION T	0:		SUBSEQUENT RE	PORT OF:						
DEDECOR DEMENDAN	WOOK TI BUT	JG AND ABANDON X	DEMEDIAL WO	אסע	T ALTERIA						
PERFORM REMEDIAL TEMPORARILY ABAN		NGE PLANS	REMEDIAL WO	RILLING OPNS.		NG CASING					
PULL OR ALTER CA	· · · · · · · · · · · · · · · · · · ·			AND CEMENT JOB	1200 %	ND ABANDONMENT					
OTHER			OTHER			<u></u>					
			J			ļ					
Describe Proposed of	or Completed Operat	lons(Clearly state a	ll pertinent d	details, and give	pertinent date	es. including esti-					
		ork) SEE RULE 1103.		, 3	•	,					
* 1)	Set CIBP @ 3250)', spot 35' cmt.									
2)	Cut csg @ 2300'	. pull csa.									
	3	54									
	Spot 100' plug, 35sx, 2250'-2350', half-in & half-out csg stub, tag plug € 2250'.										
3)	Spot 100' plug, 35sx, 1250'-1350', tag plug @ 1250'.										
3)	Spot 100' plug,	35sx, 1250'-1350',	ing ping o im-			Spot 100' plug, 50sx, 300'-400', tag plug @ 300'.					
		•		,							
4)	Spot 100' plug,	•	g plug @ 3001.								

Original Signed By Leslie A. Clements

Supervisor District II

TITLE

DATE APR 1 8 1983

* NOTIFY ORD 24 HRS PRIOR TOSETTING BIM PLUC MUD BOTWEEN ALL PLUGS

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY: