

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-015-10889

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
E 8560

7. Lease Name or Unit Agreement Name:
Southern Union State

8. Well No. 1

9. Pool name or Wildcat
Mesa Queen Associated

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
4387' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Remuda Operating Company

3. Address of Operator
301 N. Colorado Ste 150

4. Well Location
Unit Letter J : 2310 feet from the South line and 2310 feet from the East line
Section 13 Township 16S Range 31E NMPM County Eddy

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

8 5/8 " csg set @ 433' w/225 sx, 4 1/2" csg set @ 3666' w/145 sx (6 3/4" hole),
2 3/8" tbq @ 3368', perfs @ 3358-70'

25 Plugging procedure: TAG

Spot 20 sx plug @ 3368'. Cutoff & pull 4 1/2" csg. Spot 35 sx @ cutoff & tag.
Spot 35 sx plug @ 2350-2250' & tag, 35 sx plug @ 1435-1335' & tag, 50 sx plug @ 483-383' & 10 sx plug @ surface.

* Bring gel between cement plugs.
Notice N.M.O.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tom Aylesworth TITLE President DATE 1/19/2001

Type or print name Tom Aylesworth

(This space for State use)

Telephone No. 915-684-8003

APPROVED BY Mike Sturfield

Conditions of approval, if any:

TITLE Field Rep. II

DATE 2/9/2001