

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN DUPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC 063927

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Anadarko Production Company		8. FARM OR LEASE NAME Ets Federal
3. ADDRESS OF OPERATOR		9. WELL NO. 3
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FEL & 1650' FSL Sec. 19, T 16 S, R 31 E Eddy County, New Mexico		10. FIELD AND POOL, OR WILDCAT Square Lake
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 19, T 16 S, R 31 E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3872 GL		12. COUNTY OR PARISH Eddy
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☒	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) Well Completion	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled well to TD 3350 KB Ran Gamma-Density-Caliper log. Ran log* 10.5# J-55 API Casing, set at 3338 GL, cemented with 300 sz. Ran correlation and collar logs, perforated 1/ft at 3170, 71, 72, 76, 79, 82, 83, 88, 3286, 87, 88, 92, 93, 94, 3304, 05. Ran tubing & straddle packers set at 3154 and 3196. Fracture treated each zone with 500 gal 15% Hcl, 15,000 gal gelled brine and 15,000# 20-40 sand. Premier zone 3170-88 treated 16.8 BPM Max press 4800, ISDP 2500. 15 min shut in 2100 psi. Lovington zone 3286-3304 treated 15.8 BPM at 5000 psi. ISDP 2500, 15 min 1900 psi. Pulled packers, sand pumped frac sand, ran tubing rods & pump. Preparing to put on pump. Work completed on March 28, 1968.

RECEIVED
APR-41968
U. S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED D. R. Layton
(This space for Federal or State office use)

TITLE **District Superintendent**

DATE **2 April 1968**

APPROVED BY
CONVENTIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
APR 5 - 1968
R. L. GILMAN
ACTING DISTRICT SUPERINTENDENT

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.