

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT 1
(Other ins.
verse side)REPLICATE*
tions of re-Form approved.
Budget Bureau No. 42-R1424.

Copy to S.F.

5. LEASE DESIGNATION AND SERIAL NO.

NM-1135-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ INCOMPLETE

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 88, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FNL x 1980' FWL Sec. 11 (Unit F (2 1/4 NW 1/4))

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3583' R.D. B.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

11-16-28-NMPM

12. COUNTY OR PARISH 13. STATE

EDDY

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

On 1-10-65, 5 1/2" OD 14-15.5" J-55 N-80 casing was run and set @ 9670' (TD) w/ 5500 yd Infurno + 5% HALAD 9. After 720C appx 72 hrs. Tested casing with 3000 psi. Test OK. Perforated Morrow 9266-9282' w/ 215 SF. Acidized w/ 1000 gal 15%. Traced w/ 60,000 gal mod. prime + 42000# sand. Evaluated no oil. Shift show of Res. Now Commercial. Proposal to abandon Morrow, plug back, pull 5 1/2" casing, perforate + evaluate Queen zone: Spst 50 yd plug across perfs 9266-82'; Shoot + pull 5 1/2" from appx 8200'; 50 yd In + out of 5 1/2" stub; 50 yd plugs 50' above + below formation - TCANYON-8072; TWOLF CAMP-6814; TABO-5360; DRINKARD-4564; TGLOR-3365; 50 yd In + out of 9 1/2" hole @ 1980'; Set CIBPO 1350'. PERF. QUEEN ZONE 1128-36. Acidize + evaluate as necessary in attempting production.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE 1-24-69

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

JAN 23
R. L. BECKME

*See Instructions on Reverse Side

RECEIVED

JAN 29 1969

O. C. C.

04- USGS-ART
1- NBW
1- SUSP
1- RRY
1- ATL
1- SHELL
1- TESORO
1- STATE LAND