

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other instructions on re-
verse side)Form approved
Budget Bureau No. 42-R1400

5. LEASE DESIGNATION AND SERIAL NO.

NM-1135

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ DRY HOLE	7. UNIT AGREEMENT NAME NORTH CROW FLATS FEDERAL UNIT
2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR BOX 68, HOBBS, N. M. 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 1980' FWL Sec 11 (Unit F, SE 1/4 T14N4E)	10. FIELD AND POOL, OR WELLCAT WELLCAT
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 11-16-28 NMPM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3583' R.D.B.	12. COUNTY OR PARISH EDDY
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Abandoned Morrow and plugged back and tested Queen as follows: Spot 50 s4 plug across perfs 9266-86'. Shot 5 1/2" casing @ 8200, 7900, and pulled from 7300. Spotted 50 s4 cement plug @ 7350, 6860, 5400, 4600, 3400, & 2020. Set CI BPE @ 1350. QUEEN. Perforated intervals 1128-36'. Flowed salt water immediately. No show of oil or gas.

Abandoned well as follows: (2-7-69 DIA)
Spotted 100 s4 cement plug across perfs (1128-36)
Spotted 10 s4 @ surface and erected P+A marker.

Final cleanup shall be made and ground restored contour.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

FEB 12 1969

(This space for Federal or State office use)

4- USGS-A2

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

JUN 5 - 1969

R. L. BECKMAI

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

1- NSU
1- SUSP
1- REV
1- ATL
1- SHELL
1- TESORO
1- STATE LAND
2- W. F. SPENCER