

NEW MEXICO OIL CONSERVATION COMMISSION
DRAWER 100
ARTESIA, NEW MEXICO

FIELD REPORT FOR CEMENTING OF WELLS

Operator <i>Yates Pct. Corp.</i>		Lease <i>Jackson AT</i>		Well # <i>3</i>	
Location of Well	Unit <i>K</i>	Section <i>14</i>	Township <i>17</i>	Range <i>25</i>	County <i>Eddy</i>
Drilling Contractor <i>Co. Tools</i>			Type of Equipment <i>ROT</i>		

APPROVED CASING PROGRAM

Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement
<i>9 7/8</i>	<i>7</i>	<i>23</i>		<i>1100</i>	<i>Circ</i>
<i>6 1/4</i>	<i>1000 5 1/2</i> <i>400 4 1/2</i>	<i>15.5 + 7.5</i>		<i>1500</i>	<i>Circ</i>

Casing Data: *17 Youngstown J 55*
Surface *30* joints of *7* inch # *13 API Grade C ? 10 Thread*
(Approved) (~~Rejected~~)

Inspected by *Stamets & Grossarth* date *1-6-71*

Cementing Program

Size of hole *12 1/4 125* *7 1/2 1150* Size of Casing *7* Sacks cement required

Type of Shoe used *Texas* Float collar used *baffle* Btm 3 jts welded

TD of hole *1150* Set Feet of *7* Inch # Grade

New-used csg. @ *TD* with *100* sacks neat cement around shoe *2% Ca C 1/2*

+ *350* sax *Incer* additives *2000 # Gilmite, 750 gal, 100 # Cellphane*

Plug down @ *4:00* (AM) (PM) Date *1-7-71*

Cement circulated *✓* No. of Sacks *60*

Cemented by Witnessed by

Temp. Survey ran @ (AM) (PM) Date top cement @

Casing test @ (AM) (PM) Date

Method Used Witnessed by

Checked for shut off @ (AM) (PM) Date

Method used Witnessed by

Remarks: *Cement dropped out of sight when plug down. 1-8-71 tag up with 1" tbg at 60'. To fill with ready mix.*