

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.  
**WM 2507**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ **DRY HOLE**

2. NAME OF OPERATOR

**MORRANTO COMPANY**

3. ADDRESS OF OPERATOR

**101 North Marlenfeld, Midland, Texas 79701**4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface**2080' FWL, 1500' FWL**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

**3950' Gr.**

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

**TRIGO - FEDERAL**

9. WELL NO.

**1-Y**

10. FIELD AND POOL, OR WILDCAT

**WILDCAT**11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA**Sec. 7, T-16N, R-31E**

12. COUNTY OR PARISH

**EDDY**

13. STATE

**NEW MEXICO**

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☒ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

**This well was drilled to a total depth of 9213' and plugged and abandoned as follows:****1/16/72 Set five 35 Sx. cement plugs as follows:  
9000-8900'; 8000-7900'; 6600-6500'; 4700-4600; 3250-3150';****1/17/72 Cut off 8 5/8" casing at 1250' and pulled, pumped 300 Sx. cement plug to 1250'.  
Set 100 Sx. cement plug 590-428'.  
Shut in 22 Hrs.; held OK, no water flow.****1/18/72 Set 5 Sx. cement plug at surface w/ 4" x 4' pipe marked at surface with location marked thereon.  
Hole was filled w/ 10# mud between plugs.****You will be notified when location is cleaned up and ready for inspection.****RECEIVED****JAN 27 1972****U. S. GEOLOGICAL SURVEY****ARTESIA, NEW MEXICO****1/25/72**

18. I hereby certify that the foregoing is true and correct

SIGNED **A. W. Wood**TITLE **District Production Mgr.**

DATE

(This space for Federal or State office use)

TITLE

DATE

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:**APPROVED**  
**DEC 18 1971**  
**H. L. BEEKMAN**  
**ACTING DISTRICT ENGINEER**

\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.