NO. OF COPIES RECEIVED	_			Form C-103	·
DISTRIBUTION	-	•		Supersedes Oi C-102 and C-1	
SANTA FE	NEW MEXIC	O OIL CONSERVATION CO	MMISSION	Effective 1-1-	
FILE					
U.S.G.S.		0 5 1	SEIVED	5a, Indicate Type	Fee. X
LAND OFFICE		K = .		State 5. State Oil & Ga	
OPERATOR /		r.r	B 5 1975	3. Style Off a Ga	a Dagga Ma,
				mmm	mmmm
SUND GO NOT USE THIS FORM FOR P	RY NOTICES AND RE	EPORTS ON WELLS	ENT RESERVOIR.		
USE "APPLICA	ATION FOR PERMIT 2" (FORM	C-101) FOR SUCH PROPOSALS.)	ESIA, OFFICE	7. Unit Agreemen	it Name
OIL GAS WELL Y	OTHER-	AR	EBIA, O		
2. Name of Operator				8. Farm or Lease	
Hanson Oil Corpo	oration,			Clyde Guy	Comm.
3. Address of Operator	- 22 N N			9. Well No	
	Roswell, New Mex	(100 88201		# 1	ol or Wilden
4. Location of Well	3.000	Courth 6	:60¹		arms Morrow
UNIT LETTER	1980 FEET FROM THE	South LINE AND	FEET FRO	" Keilledy 1	
F1	3/1	SHIPRANGE	26-E		
THE East LINE, SEC	TION JOWN	SHIPRANGE	NMPA	<i>«()))))))</i>	
	15. Elevation	(Show whether DF, RT, GR, et	c.)	12, County	
		N.K.		Eddy	VIIIIIII
NOTICE OF	INTENTION TO:	D Indicate Nature of No	SUBSEQUEN	NT REPORT OF:	RING CASING AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE	PLANS CASING TEST	AND CEMENT JOB	·	
Political distributions of the control of the contr		OTHER	Whipstock # オ	<i>·</i> ·	X
STHER		[_]		•	
17. Describe Proposed or Completed	Operations (Clearly state o	all pertinent details, and give p	ertinent dates, includi	ng estimated date of	starting any proposed
work) SEE RULE 1103.	Optications (= 1.7)				
1-8-75 Set whipstock	@ 7614' & drille	d out.	•		
2-3-75 T.D. 8908', ra	an Comp. Neutron	& Density Log.			
D.S.T. from 8	8822' to 8908'				
D.3.1.				00	
first flow I.	H. 4382	Second flow		98 70	
I.				72 49	
F.1		•	F.H. 45		
I.S.I.	P 791		, , , , , , , , ,		

12. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SINES VICE President - Production DATE 2/3/75

SUPERVISOR, DISTRICT II

CONDITIONS OF APPROVAL, IF ANY: