

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

FEB 10 1975

**O. C. C.**  
**ARTESIA, OFFICE**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Hanson Oil Corporation	8. Farm or Lease Name Clyde Guy Comm.
3. Address of Operator P.O. Box 1515 Roswell, New Mexico 88201	9. Well No. # 1
4. Location of Well UNIT LETTER <u>I</u> , 1980 FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>34</u> TOWNSHIP <u>17-S</u> RANGE <u>26-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Undes- Morrow</u>
15. Elevation (Show whether DF, RT, GR, etc.) N. K.	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-6-75 Well was plugged as follows: Run drill pipe in hole, set w/ C1 H cement.

Plug No.	Sacks	Depth of Plug bottom to top-
1	35	8782 - 8682'
2	35	7097 - 6997'
3	35	5716 - 5616'
4	35	4094 - 3994'
5	35	2406 - 2306'
6	35	1563 - 1463'
7	15	Surface

Hole was filled with mud between plugs.

Pits will be filled, location levelled, and cleared of junk.

*Posted  
ID-2  
2-21-75  
Posted  
ID-4  
5-30-75*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ray W. H. TITLE Vice President - Prod. DATE 2-7-75

APPROVED BY John Harris TITLE OIL AND GAS INSPECTOR DATE MAY 14 1975

CONDITIONS OF APPROVAL, IF ANY: