ref r	COPIES RECEIVED 3]	RECEIVED	Form C-103 Supersedes Old C-102 and C-103	· .	
Listo of Fice	FE 1	NEW MEXICO OIL CON	SERVATION COMMISSION	Effective 1-1-65		
Listo of Fice	FILE	-	AUG 7 1974	5a, Indicate Type of L	ease	
CPERATOR U. C. C. S. Busto CU. & Case Lessen No. ID early SUNDRY NOTICES AND REPORTS ON WELLS S. Busto CU. & Case Lessen No. ID early SUNDRY NOTICES AND REPORTS ON WELLS I. Luit Agreement Name ID early State Comparison of the state of the st		-				
Image: Supprise of the second seco		-	0. 0. 0	5. State Oil & Gas Lea	ase No.	
Image: And the state in the state of the state in th	UPERATOR		ARTESIA, LEIT			
Image: State of the stage: a state diftill the stage: a state of the stage: a s	SUNDE (DO NOT USE THIS FORM FOR PRI- USE "APPLICAT	RY NOTICES AND REPORTS ON OPOSALS TO DRILL OR TO DELEAN OR PLUG	WELLS BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)			
1. The second decrement of the second decrement d		and the second	AEPONT	7. Unit Agreement Nar	ne	
Yates Petroleum Corporation Achem-Frey "DM" 1. Address di Statuti 207 South 4th Street-Artesia, NM 88210 3 1. Locuitar di Well 10. Field aud Pool, or Wildent Und Vest 13. Millent III Vest 13. Millent III Vest 13. TownEnir Vest 13. TownEnir Vest 13. TownEnir Vest 13. TownEnir Vist Letter 13. TownEnir Vist Rule aud Town 13. TownEnir Vist Rule aud Towo		OTHER-		8. Farm or Lease Nam	ie	
1. Addred of Cymeter 9. Well No. 207 South 4th Street-Artesia, NM 88210 3 4. Location of Well 10. Field and Pool, at Vilacet Und 5. Location of Well 10. Field and Pool, at Vilacet Und THE N 660 THE 13 TOMESHIP THE 14. 13 THE 15. Elevation (Show whether DF, RT, GR, etc.) 14. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: Elevation The State This App Cryptice These Tomestate Casince The Mediat Work THE MEDIAL WORK THE AND ENDERT Attraine casince THE MEDIAL WORK The Mediate Operation (Clearly state all perinent detalls, and give pertinent dates, including e		Corporation		Achen-Frey	"DM"	
207 Solidin 4 Chi Scheel-Anticesia, in Collog 10. Field and Pool, or Wilacat Und 5. Lection of Wall N 660 wret N 660 wret 13 Townswip 15. Elevation of Wall 175 Fasce wret West 13 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: Put on Altrs cashe Put on Altrs cashe Put on Altrs cashe Put on Altrs cashe OTHER Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: Put on Altrs cashe Put on Altrs cashe OTHER Check Appropriate Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed OTHER Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) Start RULL 103. Stage - Stage: Stage: Stage: Stage: Stage: Stage: Stage: Stage: Theteload Completed Operat				9. Well No.		
1. Location of Well N 660 reff FROM THE	207 South 4th St	_				
UNIT LETTER 13 175 25E MARKE THE 13 10000 Her 175 RANCE 25E MARKE 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: 12. County Eddy PERFORM REVEDIAL WORK PLUE AND ABANDON PLUE AND ABANDON ALTERING CASING PLUE AND ABANDON PULL OR ALTER CASING PLUE AND ABANDON CHARKE PLANS Configure Casing ALTERING CASING 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent detail, including estimated date of starting any proposed THE Starge: - 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent detail, including estimated date of starting any proposed THE Starge: - Set Packer 2908-2982' & acidized w/250g 15% acid - swabbed dry. <u>3rd Stage -</u> Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3th Stage: Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. Sth Stage: - Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. Sth Stage: Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. Sth Stage: - Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. Sth Stage: Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry.			1000		ł	
THE THE THE LINE, SECTION TOWNSHIP RAREE MARKE 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: Attening casing 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: Attening casing 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed with SEG RULE 1103. Attening casing any proposed if Starting any proposed if Notice 112 Starting any proposed with SEG RULE 113. 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed with SEG RULE 113. Its Starge: - 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed with SEG RULE 113. Its Starge: - 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed with SEG RULE 113. 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed withese SEG RULE 113. 18.	UNIT LETTER N	560 FEET FROM THE	LINE AND FEET FROM	Eagle Creek	S.A.	
15. Elevation (Show whether DF, RT, GR, etc.) 12. County 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON PLUG AND ABANDON REMEDIAL WORK OTHER Commence of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed 07MER Discribe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed 17. Bescribe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of	West Line, sect	13 TOWNSHIP 17	5 <u>25E</u> NMPM.			
3452' GR Eddy 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUE AND ABANDON REMEDIAL WORK Alterine CASING PULL OR ALTER CASING PLUE AND ABANDON REMEDIAL WORK Alterine CASING PULL OR ALTER CASING PLUE AND ABANDON REMEDIAL WORK Alterine CASING OTHER CHANGE PLANS CHANGE PLANS Alterine Casing of the proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of staring any proposed works of the proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of staring any proposed works of the proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of staring any proposed works of the proposed of the proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of staring any proposed works of the proposed of the proproposed of the proposed of the proproposed of the propr	······			12. County	<i>66666</i>	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TENFORM REMEDIAL WORK CHARGE PLANS CHARGE PLANS OTHER THE CASING PLUG AND ABANDON REMEDIAL WORK CHARGE PLANS CHARGE PLANS COMMENCE DRILLING OPNS. OTHER Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. TD 8430'; PBTD 3100' - Acidized well in 6 stages as follows: lst Stage: - Set Packer 2908-2982' & acidized w/250g 15% acid - swabbed dry. 2nd Stage - Set Packer 2558-2632' & acidized w/250g 15% acid - swabbed dry. Set packer 2558-2632' & acidized w/250g 15% acid - swabbed dry. Set packer 2009-2982' & acidized w/250g 15% acid - swabbed dry. Set packer 208-2982' & acidized w/250g 15% acid - swabbed dry. Set packer 208-2982' & acidized w/250g 15% acid - swabbed dry. Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. <td colspan<="" td=""><td></td><th></th><th></th><td>1 N</td><td></td></td>	<td></td> <th></th> <th></th> <td>1 N</td> <td></td>				1 N	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REWEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPHS. ALTERING CASING OTHER CHANGE PLANS CHANGE PLANS CASING THE PLUG BACK to San Andres, set X 17. Describe Proposed or Completed Operations (Clearly state all periment details, and give pertiment dates, including estimated date of starting any proposed works) SEE RULE 103. TD 8430'; PBTD 3100' - Acidized well in 6 stages as follows: lst Stage: - Set Packer 2908-2982' & acidized w/250g 15% acid - swabbed dry. 2nd Stage - Set Packer 2908-2982' & acidized w/250g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/250g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-25				her Data		
<pre>PLUG AND ADARDON PULLO AND ADARDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ADARDONMENT CHANGE PLANS COMMENCE DRILLING OPNS. CASING THE PLUG BACK to San Andres, set X prod csg, perf, & sand frac.</pre>			SUBSEQUENT	REPORT OF:		
<pre>PLUG AND ADARDON PULLO AND ADARDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ADARDONMENT CHANGE PLANS COMMENCE DRILLING OPNS. CASING THE PLUG BACK to San Andres, set X prod csg, perf, & sand frac.</pre>	_					
TELEPOARTICY ABANDON PULL OR ALTER CASING OTHER OTHER OTHER II. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed works SEE RULE 1103. TD 8430'; PBTD 3100' - Acidized well in 6 stages as follows: Ist Stage: - Set Packer 2908-2982' & acidized w/250g 15% acid - swabbed dry. 2nd Stage - Set packer at 2480-2550' & acidized w/250g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. 3rd Stage - Set packer 1965-2039' & acidized w/500g 15% acid	PERFORM REMEDIAL WORK	PLUG AND ABANDON				
prod csg, perf, & sand frac. 17. Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. TD 8430'; PBTD 3100' - Acidized well in 6 stages as follows: <u>lst Stage: -</u> Set Packer 2908-2982' & acidized w/250g 15% acid - swabbed dry. <u>2nd Stage -</u> Set packer 2558-2632' & acidized w/250g 15% acid - swabbed dry. <u>3rd Stage -</u> Set packer at 2480-2550' & acidized w/500g 15% acid - small show of gas. <u>4th Stage:</u> - Set packer 2131-2205' & acidized w/500g 15% acid - swabbed dry. <u>5th Stage:</u> - Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage:</u> - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. After no production was encountered Plugged Back to 1536' w/35 sacks Class C cement at 1640-1536', heavy mud from 3100'-1640'. (San Andres). PBTD 1536' Ran 19 jts of 4½" 9.5#, J-55 casing (767') and 19 jts of 5½" 15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement 1-Howco float shoe, 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00	r=1	CHANGE PLANS				
prod csg, perf, & sand frac. 17. Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. TD 8430'; PBTD 3100' - Acidized well in 6 stages as follows: <u>lst Stage: -</u> Set Packer 2908-2982' & acidized w/250g 15% acid - swabbed dry. <u>2nd Stage -</u> Set packer 2558-2632' & acidized w/250g 15% acid - swabbed dry. <u>3rd Stage -</u> Set packer at 2480-2550' & acidized w/500g 15% acid - small show of gas. <u>4th Stage:</u> - Set packer 2131-2205' & acidized w/500g 15% acid - swabbed dry. <u>5th Stage:</u> - Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage:</u> - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. After no production was encountered Plugged Back to 1536' w/35 sacks Class C cement at 1640-1536', heavy mud from 3100'-1640'. (San Andres). PBTD 1536' Ran 19 jts of 4½" 9.5#, J-55 casing (767') and 19 jts of 5½" 15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement 1-Howco float shoe, 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00	PULL OR ALTER CASING		Test & treat Ye	eso Formatio San Andres	set_X	
17. Describe Proposed or Completed Operations (Clearly state all periment details, and give pertiment dates, including estimated date of starting any proposed work) SEE RULE 1103. TD 8430'; PBTD 3100' - Acidized well in 6 stages as follows: <u>lst Stage: -</u> Set Packer 2908-2982' & acidized w/250g 15% acid - swabbed dry. <u>2nd Stage -</u> Set packer 2558-2632' & acidized w/250g 15% acid - swabbed dry. <u>3rd Stage -</u> Set packer at 2480-2550' & acidized w/250g 15% acid - swabbed dry. <u>3rd Stage -</u> Set packer at 2480-2550' & acidized w/500g 15% acid - swabbed dry. <u>5th Stage: -</u> Set packer 2131-2205' & acidized w/500g 15% acid - swabbed dry. <u>5th Stage: -</u> Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage: -</u> Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage: -</u> Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. <u>7000000000000000000000000000000000000</u>	OT HE R		prod csg, per:	f, & sand fr	ac.	
<pre>work) SEE RULE 1103. TD 8430'; PBTD 3100' - Acidized well in 6 stages as follows: lst Stage: - Set Packer 2908-2982' & acidized w/250g 15% acid - swabbed dry. <u>2nd Stage -</u> Set packer 2558-2632' & acidized w/250g 15% acid - swabbed dry. <u>3rd Stage -</u> Set packer at 2480-2550' & acidized w/500g 15% acid - small show of gas. <u>4th Stage:</u> - Set packer 2131-2205' & acidized w/500g 15% acid - swabbed dry. <u>5th Stage:</u> - Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage:</u> - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage:</u> - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. <u>After no production was encountered Plugged Back to 1536' w/35 sacks Class C cement at 1640-1536', heavy mud from 3100'-1640'. (San Andres). PBTD 1536' Ran 19 jts of 4½" 9.5#, J-55 casing (767') and 19 jts of 5½" 15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement l-Howco float shoe, 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00</u></pre>			trile and size partinent dates including	estimated date of start	ing any proposed	
<pre>Set Packer 2908-2982' & acidized w/250g 15% acid - swabbed dry. <u>2nd Stage -</u> Set packer 2558-2632' & acidized w/250g 15% acid - swabbed dry. <u>3rd Stage -</u> Set packer at 2480-2550' & acidized w/500g 15% acid - small show of gas. <u>4th Stage:</u> - Set packer 2131-2205' & acidized w/500g 15% acid - swabbed dry. <u>5th Stage:</u> - Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage:</u> - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage:</u> - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. <u>After no production was encountered Plugged Back to 1536' w/35 sacks Class C</u> cement at 1640-1536', heavy mud from 3100'-1640'. (San Andres). PBTD 1536' Ran 19 jts of 4½" 9.5#, J-55 casing (767') and 19 jts of 5½" 15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement 1-Howco float shoe. 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00</pre>	work) SEE RULE 1103.					
<pre>Set packer 2558-2632' & acidized w/250g 15% acid - swabbed dry. <u>3rd Stage -</u> Set packer at 2480-2550' & acidized w/500g 15% acid - small show of gas. <u>4th Stage:</u> - Set packer 2131-2205' & acidized w/500g 15% acid - swabbed dry. <u>5th Stage:</u> - Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage:</u> - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. <u>After no production was encountered Plugged Back to 1536' w/35 sacks Class C</u> cement at 1640-1536', heavy mud from 3100'-1640'. (San Andres). PBTD 1536' Ran 19 jts of 4½" 9.5#, J-55 casing (767') and 19 jts of 5½" 15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement l=Howco float shoe. 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00</pre>	TD 8430'; PBTD 3100'	' - Acidized well in	6 stages as follows	: <u>Ist Stage</u>	<u>: -</u>	
<pre>Set packer at 2480-2550' & acidized w/500g 15% acid - small show of gas. <u>4th Stage:</u> - Set packer 2131-2205' & acidized w/500g 15% acid - swabbed dry. <u>5th Stage:</u> - Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage:</u> - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. After no production was encountered Plugged Back to 1536' w/35 sacks Class C cement at 1640-1536', heavy mud from 3100'-1640'. (San Andres). PBTD 1536' Ran 19 jts of 4½" 9.5#, J-55 casing (767') and 19 jts of 5½" 15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement 1-Howco float shoe. 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00</pre>	Set Packer 2908-2982' & acidized w/250g 15% acid - swabbed dry. 2nd Stage -					
<u>4th Stage:</u> - Set packer 2131-2205' & acidized w/500g 15% acid - swabbed dry. <u>5th Stage:</u> - Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage:</u> - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. <u>After no production was encountered Plugged Back to 1536' w/35 sacks Class C</u> <u>cement at 1640-1536', heavy mud from 3100'-1640'. (San Andres).</u> <u>PBTD 1536'.</u> - Ran 19 jts of 4½" 9.5#, J-55 casing (767') and 19 jts of 5½" <u>15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C</u> cement <u>1-Howco float shoe. 5 centralizers at 1495, 1455, 1415, 1375, 1335'.</u> PD 4:00	Set packer 2558-2632' & acidized w/250g 15% acid - swabbed dry. 3rd Stage -					
<u>5th Stage:</u> - Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry. <u>6th Stage:</u> - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. After no production was encountered Plugged Back to 1536' w/35 sacks Class C cement at 1640-1536', heavy mud from $3100'-1640'$. (San Andres). PBTD 1536' Ran 19 jts of $4\frac{1}{2}$ " 9.5#, J-55 casing (767') and 19 jts of $5\frac{1}{2}$ " 15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement 1-Howco float shoe. 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00	Set packer at 2480-2550' & acidized w/500g 15% acid - small show of gas.					
6th Stage: - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. After no production was encountered Plugged Back to 1536' w/35 sacks Class C cement at 1640-1536', heavy mud from 3100'-1640'. (San Andres). PBTD 1536' Ran 19 jts of 4½" 9.5#, J-55 casing (767') and 19 jts of 5½" 15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement 1-Howco float shoe. 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00	4th Stage: - Set packer 2131-2205' & acidized w/500g 15% acid - swabbed dry.					
6th Stage: - Set packer 1965-2039' & acidized w/500g 15% acid - swabbed dry. After no production was encountered Plugged Back to 1536' w/35 sacks Class C cement at 1640-1536', heavy mud from 3100'-1640'. (San Andres). PBTD 1536' Ran 19 jts of 4½" 9.5#, J-55 casing (767') and 19 jts of 5½" 15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement 1-Howco float shoe. 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00	5th Stage: - Set packer 2059-2131' & acidized w/500g 15% acid - swabbed dry.					
After no production was encountered Plugged Back to 1536' w/35 sacks Class C cement at 1640-1536', heavy mud from $3100'-1640'$. (San Andres). PBTD 1536' Ran 19 jts of $4\frac{1}{2}$ " 9.5#, J-55 casing (767') and 19 jts of $5\frac{1}{2}$ " 15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement 1-Howco float shoe. 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00	6th Stage: - Set packer 1965-2039' & acidized w/Soug 15% acid - Swabbed dry.					
PBTD 1536' Ran 19 jts of $4\frac{1}{2}$ " 9.5#, J-55 casing (767') and 19 jts of 5%" 15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement 1-Howco float shoe, 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00	After no production	was encountered Plu	gged Back to 1536' w	/35 sacks CI	.ass C	
15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement 1-Howco float shoe, 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00	cement at 1640-1536	', heavy mud from 31	00'-1640'. (San Andr	es).	c c] u	
15.5#, K-55 casing (756') (Total 1523') set at 1536' w/250 sacks Class C cement 1-Howco float shoe, 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00	PBTD 1536' Ran	19 jts of 4날" 9.5#,	J-55 casing (767')	and 19 jts o	of 5%"	
1-Howco float shoe, 5 centralizers at 1495, 1455, 1415, 1375, 1335'. PD 4:00	15.5#, K-55 casing	(756') (Total 1523')	set at 1536' w/250	sacks Class	C cement.	
$p = \pi - 7 - 4 - 74$ were labours and tested casing to 1000#. OK. Perforated w/34	1-Howco float shoe.	5 centralizers at 1	495, 1455, 1415, 137	5,1335'. P	PD 4:00	
P.M. 7-4-74. Wee 10 hours and costed cooling to a	P.M. 7-4-74, WOC 1	8 hours and tested c	asing to 1000#. OK.	Perforated	w/34	
.41" jets shots 1335-1501' and Sand Frac'd w/3000 gallons of acid for breakdown	.41" jets shots 133	5-1501' and Sand Fra	c'd w/3000 gallons o	f acid for f	preakdown,	
80000 gallons treated water, 55000# 20-40 sand and 25000# 10-20 sand.	80000 gallons treat	ed water, 55000# 20-	40 sand and 25000# 1	0-20 sand.		
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	10. Thereby and if y that the information	on above is true and complete to the bes	t of my knowledge and belief.			
	To Thereby Certify that the monimula					
SIGNED GAR WAY WAY WAY WAY WAY TITLE Engineer DATE 8-6-74	SIGNED CALLON VANTA	glive TITLE	Engineer	<u>DATE</u> 8-6-	-74	
al a greater TITLE OIL AND GAS INSPECTOR AUG 7 1974						

CONDITIONS OF APPROVAL, IF ANY:

-