Ent. K		WINGTON, NEW N		W74-770
york		TORY WATER	RANALYSIS	
To Yates Petroleum Corroration			Date_	10-20-74
207 S. 4th Street				rty of Halliburton Company and neither nor a copy thereof is to be published
Artesia, New Mexic	0		of laboratory managem	t securing the express written approva- ent; it may however, be used in the
		· · · · ·	course of regular business operations by any person or conce and employees thereof receiving such report from Halliburt Company.	
Submitted by I-	10-17-25		Date Rec	10-20-74
Well No. Airport C.F.		1158-1163	Formation	
CountyEddý	Field		Source_	Salt Water flow
	10-18-74			
Resistivity	ND	, 		· · · · · · · · · · · · · · · · · · ·
Specific Gravity	1.090			
pH				
Calcium (Ca)	• • • • •			*MPI
Magnesium (Mg)	90			
Chlorides (Cl)	77,500			· · · · · · · · · · · · · · · · · · ·
Sulfates (SO .)	3,740			
Bicarbonates (HCO <sub>3</sub> )	Nil			
Soluble Iron (Fe)	Nil			RECEIVED
Carbonate, $\omega_3$	240			<u>NOV-2-6-1974</u>
Hydroxide, OH	545			<u> </u>
				ARTESIA, OFFICE

Respectfully submitted,

Analyst: Brewer

¢

HALLIBURTON COMPANY
111 - Binney
ByCHEMIST

NOTICE

This report is limited to the described sample tested. Any user of this report agrees that Halliburton shall not be liable for any loss or damage, whether it be to act or omission, resulting from such report or its use.