NO. OF COPIES RECEIVED	3		
DISTRIBUTION			
SANTA FE			
FILE	/	1	
U.S.G.S.			
LAND OFFICE			
OPERATOR	1		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65

FILE	/	1		,		The first feet	Text 10 000 100				
u.s.g.s.				•		K E L	EIVE		5a. Indicate T	ype of Lease	
LAND OFFICE	<u> </u>					_			State X	Fee	
OPERATOR							27 1976		1	Gas Lease No. 47	
(DO NOT USE THIS FO USE	SU	NDR'	Y NOTICES	AND REPO	ORTS ON	WELLS	HENT RESERVOIS	١.			
OIL X GAS WELL	_]	OTHER-				A. DFFICE			nent Name O Pressure	
2. Name of Operator				/					8. Form or Lec	ce Project	
Atlantic Richfie	ld	Comp	pany 🗸						Empire Ab	o Unit "E"	
3. Address of Operator		-							ч. Well No.		
• P. O. Box 1710,	HOL	obs,	New Mexi	co 88240	·				382	· · · · · · · · · · · · · · · · · · ·	
-		1 1	216		Wort		1100		10. Field and Pool, or Wildeat		
UNIT LETTER	<u> </u>		316 FEET	T FROM THE	west	LINE AND	11/5	FEET FROM	Empire A	DO ***********	
THE North	INE, :	5EC T101	N35	TOWNSHIF	, <u> </u>	RANGE _	28E	NМРМ.			
	III	IIII	15.	Elevation (Sh	ow whether	DF, RT, GR, e	etc.)		12. County	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	77,			3	684.3'	GR			Eddy		
16.	Che	ck A	ppropriate	Box To In	dicate N	ature of No	otice, Repo	rt or Oth	·		
NOTIC			TENTION T						REPORT OF	F:	
	_										
PERFORM REMEDIAL WORK		,	,	PLUG AND ABA	ANDON .	REMEDIAL WO	RK		ALT	ERING CASING	
TEMPORARILY ABANDON]					COMMENCE DE	ILLING OPNS.		PLU	G AND ABANDONMENT	
PULL OR ALTER CASING				CHANGE PLAN	s		AND CEMENT JOE		_		
						OTHER \underline{L}	og, Perfo	<u>rate, a</u>	cidize &	complete X	
OTHER					—— L						
17. Describe Proposed or Conwork) SEE RULE 1103.	nplet	ed Ope	erations (Clear	ly state all pe	rtinent deta	ils, and give p	pertinent dates,	including	estimated date o	of starting any proposed	
Finished drlg 7-7	/8	hol	le to TD	6400¹@:	2:00 AN	7/21/76	Ran GR	-Neutro	on. Dual L	aterolog w/MSFI	
caliper, CNDT & S	oni	c $1c$	ogs. Ran	199' of	5층" OD	15.5# K-	-55 csg &	6200'	of 5 ¹ OD	14# K-55 csg	
w/DV tool @ 3997'	, S	et c	csg @ 639°	9'. Cmt	d 5 🖯 ' Օ	D csg (St	tage #1) v	v/10 bb	ls SAM-4	spacer & 25 BFV	
ahead of 575 sx 5 Opened DV tool &	0/5	0 Pc	ozmix Cl (C cmt con	nt'g 2%	gel, 8#	salt/sk.	.6% CH	FR-2, 5# G	ilsonite/sk.	
cmt ahead of 1250	SX	Cl	H cont'g	.3% Hal:	ad 22,	8# salt/s	sk, 2% Ca	Cl. Di	splaced c	mt & closed DV	
tool. Circ 110 s	х с	mt c	out.PD @	@ 6:15 Pi	M 7/22/	76. Inst	called we	llhead	7/22/76.	WOC 80 hrs.	
Drld cmt 3995-97'	&	DV t	cool @ 39	97'. Te:	sted cs	g to 1500	# for 15	mins.	OK. Ran	bit in hole to	
PBD 6355'. Circ	ho l	e w/	'96 BFW c	ont'g 2%	KCL co	nt'g 10 g	gals ARCO-	-Hib C-	198. Spo	tted 2 bbls 15%	
HCL-LSTNE acid db	1 i	nhib	across :	zone to l	be perf	'd 6114-2	24'. Ran	GR-CBI	w/MSG.	Perf'd Abo 6092	
6102' $w/2$ JSPF =	20	hole	s. RIH v	w/complet	tion as	sy consis	sting of I	l jt 2-	3/8" tail	pipe, $1 - 5\frac{1}{2}$ "	
Baker Lok-set pkr	المو مدد	вак	er Model	FL on-	-off to	ol w/1.8]	profile	e, 1 jt	; ₁ 2-3/8" t1	og & 1.81" BFC	
"F" nipple on 198	յլ Մու	S 2-	3/8 EUE	8ra J-5:	otog,	set pkr @	6010.	Swbd 5	ਰੇ hrs, red	25 BO & 25 BI	
Trtd perfs 6092-6 MP 3400#, Min 100	102 N#	W/	D vac	S 15% NC	n noc	acid con	it g iron	seques	trant, flu	ished w/12 BLC.	
perfs 6092-6102'	5 <i>n</i> ,	BO &	5 BLW of	n 3/4" cl	r, rec	100# DC	onr Siir	350#.	On 3 nr	test flwd Abo	
5800'. Perf'd Ab	o 6	050-	·6062' w/2	2 JSPF.	RTH w/	5%" BBP &	nkron 2	2-3/8"	the set	r ruc tog babu-	
tstd RBP w/2000#	for	15	mins OK,	set pkr	@ 5994	'. made 2	runs w/s	swah &	well flwd		
in 4 hrs on 3/4"	ck,	FTP	160#.	(cont d c	on atta	ched Page	#2).	,,, u.s. w	well liwa	100 BO & 20 DI	
18. I hereby certify that the in											
SIGNED	72	سعر	<u> </u>	т	ITLE Di	st. Drlg.	Supv.		DATE 8/2	26/76	
		n									
	? .	4	resser	/	S.	opervisor,	DISTRICT	Ш	AUA	3 9 0 1976	