

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

RECEIVED  
AUG 21 '90

WELL API NO. 30-015-21822
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 647
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "E"
8. Well No. 382
9. Pool name or Wildcat EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator ARCO OIL AND GAS COMPANY ✓	
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240	
4. Well Location Unit Letter C : 1316 Feet From The WEST Line and 1175 Feet From The NORTH Line Section 35 Township 17S Range 28E NMPM EDDY County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3684.3' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: TEMPORARILY ABANDON ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN.

TD 6400'; PDC 6205'; Perfs: 6170-6188'

8/16/90 MIRU. DDP. Well dead. N/D W/H N/U BOP. POH w/tbg, SN, and MA. Pick up 4-3/4" bit, 5-1/2" scrapper. RIH w/bit, scrapper and tbg. POH w/tbg, scrapper and bit. SDON.

8/17/90 R.O. Well dead. RIH w/5-1/2" CIBP, running tool, and tbg. Set CIBP. POH w/l jt tbg. R/U pump truck circulate well w/8.6# brine w/WT-675 chemical. Close well in press up to 500#. Held for 15 mins. (Chart attached.) R/D pump truck. POH w/tbg, laying down in singles and CIBP running tool. RDCL. CIBP set @ 6142.30'. Pressure test witnessed by Mike Stubblefield-NMOCD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Administrative Supervisor DATE 8/20/90

TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-3551

(This space for State Use)

APPROVED BY Harry Williams OIL AND GAS INSPECTOR DATE 8/24/90

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary  
Abandonment Expires

8/17/95

