

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N. M. & C. COPY
SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Copy to S.F.
Budget Bureau No. 12 R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME 	
2. NAME OF OPERATOR Yates Petroleum Corporation ✓		8. FARM OR LEASE NAME Federal "GI"	
3. ADDRESS OF OPERATOR 207 South 4th Street - Artesia, NM 88210		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 1980' FEL of Section 23-17S-23E		10. FIELD AND POOL, OR WILDCAT Wildcat	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 23-17S-23E Unit B NMPM	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3921' GR		12. COUNTY OR PARISH 13. STATE Eddy NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

<table style="width: 100%;"> <tr> <td style="width: 50%;">TEST WATER SHUT-OFF <input type="checkbox"/></td> <td style="width: 50%;">PULL OR ALTER CASING <input type="checkbox"/></td> </tr> <tr> <td>FRACTURE TREAT <input type="checkbox"/></td> <td>MULTIPLE COMPLETE <input type="checkbox"/></td> </tr> <tr> <td>SHOOT OR ACIDIZE <input type="checkbox"/></td> <td>ABANDON* <input type="checkbox"/></td> </tr> <tr> <td>REPAIR WELL <input type="checkbox"/></td> <td>CHANGE PLANS <input type="checkbox"/></td> </tr> <tr> <td colspan="2">(Other) <input type="checkbox"/></td> </tr> </table>	TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>		<table style="width: 100%;"> <tr> <td style="width: 50%;">WATER SHUT-OFF <input type="checkbox"/></td> <td style="width: 50%;">REPAIRING WELL <input type="checkbox"/></td> </tr> <tr> <td>FRACTURE TREATMENT <input type="checkbox"/></td> <td>ALTERING CASING <input type="checkbox"/></td> </tr> <tr> <td>SHOOTING OR ACIDIZING <input type="checkbox"/></td> <td>ABANDONMENT* <input type="checkbox"/></td> </tr> <tr> <td colspan="2">(Other) <input checked="" type="checkbox"/> Set Production csg.</td> </tr> </table>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>	(Other) <input checked="" type="checkbox"/> Set Production csg.	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>																		
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>																		
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>																		
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>																		
(Other) <input type="checkbox"/>																			
WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>																		
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>																		
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>																		
(Other) <input checked="" type="checkbox"/> Set Production csg.																			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 7085' - PBTD by Wireline 7055'.

Ran 220 joints of 4½" 10.5# K-55 (7080') of casing w/float shoe, 6 centralizers and 2 baskets set at 7080'. Cemented w/250 gallons of mud flush, 135 sacks of Class "C" w/0.5% CFR-2 and 3# KCL, 500 sacks of Halliburton-Lite 0.5% CFR-2 and 3# KCL, tailed in w/100 sacks of Class "C" 0.5% CFR-2 and 3# KCL, displaced w/40 bbls 2% KCL and 72 bbls of fresh water. PD 12:50 PM 8-3-76. WOC and tested to 1500#. OK.

Ran Temperature Survey and found top of cement at 5510'. WLPBTD 7055'.

RECEIVED

AUG 24 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Christie Tomlinson TITLE Geol. Secty DATE 8-24-76

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side