30-015-21891

This well is changing to WAShington 33 #20

IT IS THEREFORE ORDERED THAT:

Administrative Order SWD-711 ARCO Permian May 27, 1998

The applicant herein, ARCO Permian is hereby authorized to complete its Washington '33' Well No.20 located 1315 feet from the South line and 1315 feet from the West line (Unit K) of Section 33, Township 17 South, Range 28 East, NMPM, Eddy County, New Mexico, in such manner as to permit the injection of salt water for disposal purposes into the Wolfcamp and Cisco formations at approximately 6990 feet to 8680 feet through 3 1/2-inch plastic-lined tubing set in a packer located at approximately 6950 feet.

11-15-76 Dual Fateralog 55 00 - 6 7 1 3 Damma Lay-Meutron \$ 500-6712

11-2-76 Dual Laterolog 6700 - 10,490 J Comp. Neutron-Formation Odnaity 6703 - 10,492 Borchale Comp. Sonic Log 6700 10,471 0-6712 Reil 11-15-76

IT IS THEREFORE ORDERED: Case # 57/6 7-21-76 order R-5257 8-11-76

(1) That all mineral interests, whatever they may be, in the Pennsylvanian formation underlying the W/2 of Section 33,

Township 17 South, Range 28 East, NMPM, Empire Field, Eddy County, New Mexico, are hereby pooled to form a standard 320-acre gas spacing and proration unit to be dedicated to a well to be drilled at an unorthodox location 1315 feet from the South line and 1315 feet from the West line of said Section 33.

PROVIDED HOWEVER, that the operator of said unit shall commence the drilling of said well on or before the 15th day of November, 1976, and shall thereafter continue the drilling of said well with due diligence to a depth sufficient to test the Pennsylvanian formation;

PROVIDED FURTHER, that in the event said operator does not commence the drilling of said well on or before the 15th day of November, 1976, Order (1) of this order shall be null and void and of no effect whatsoever; unless said operator obtains a time extension from the Commission for good cause shown.

PROVIDED FURTHER, that should said well not be drilled to completion, or abandonment, within 120 days after commencement thereof, said operator shall appear before the Commission and show cause why Order (1) of this order should not be rescinded.

96-62-11 218 75 N

.

Simendo In 1530 MARTINGA INN-LOS ANGELES

•

.

A

÷,ř.