

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

SEP 7 1977

O. C. C.  
ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	K-6361

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plug and Abandon	7. Unit Agreement Name
2. Name of Operator Carl Engwall ✓	8. Farm or Lease Name Skelly State
3. Address of Operator P O Box 1762, Roswell, N. M. 88201	9. Well No. 1-Y
4. Location of Well UNIT LETTER C 670 FEET FROM THE N LINE AND 1650 FEET FROM THE West LINE, SECTION 11 TOWNSHIP 17 S RANGE 27 E NMPM.	10. Field and Pool, or Wildcat Und. Daugherty SA
15. Elevation (Show whether DF, RT, GR, etc.) 3397 GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged August 23, 1977

with 25 sx cement plug at 2054'  
knocked off 4 1/2" casing, pulled 800' 4 1/2" casing  
set 35 sx cement plug at 800'  
set 10 sx cement plug at top  
set dry hole marker  
Cleaned up location

99

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Shirley Hammond TITLE Agent DATE 9/1/77

APPROVED BY W.A. Gressett TITLE SUPERVISOR, DISTRICT II DATE SEP 15 1977

CONDITIONS OF APPROVAL, IF ANY: