

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-101  
Supersedes C-101  
C-102 and C-103  
Effective 1-1-77

5. Location of Well or Operation	X
6. County	
7. Well or Operation Number	K-6592, L-3093, LG-175

## SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
SEE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Name of Operator	Harvey E. Yates Company, Inc. ✓
2. Address	Suite 1000 Security National Bank Bldg., Roswell, N.M. 88201
3. Location of Well or Operation	0 990 FEET FROM THE South LINE AND 1650 FEET FROM East LINE SECTION 36 TOWNSHIP 17S RANGE 26E
4. Elevation (Show whether DF, RT, GR, etc.)	3297.0 GL
5. Location of Well or Operation	Big Boggy State
6. County	1
7. Well or Operation Number	Atoka - Penn
8. Name of Operator	Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>	REMEDIAL WORK	<input type="checkbox"/>	ABANDONING WELL	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>	COMMENCE DRILLING OPNS.	<input type="checkbox"/>	RE-ENTRY/ABANDONMENT	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	OTHER	<input type="checkbox"/>	CASING TEST AND CEMENT JOB	<input type="checkbox"/>	OTHER	<input type="checkbox"/>
				Spud and run conductor pipe X			

9. List of Operations (Clearly state all pertinent details, and give pertinent dates, including estimated dates of completion of operations. SEE RULE 1133.)

12-16-76 RU and spud - 5' progress  
12-17-76 25' TD, 20' progress, formation sand & gravel  
12-21-76 Drilling, water @ 15'-20', put on jars, hole caving TD 95', progress 40'  
12-22-76 Drilling, TD 110', progress 15', hole caving at top  
12-23-76 TD 110', hole caved in around rig, moved rig up 20' and filled in w/caliche & moved rig back over hole.  
12-27-76 TD 110' RU  
12-28-76 TD 110', Run 12' 18" line pipe, cleaning out to 40'.  
12-29-76 TD 110', Run 34.83' 16" casing. Cleaning out to 55'.  
12-30-76 TD 110', cleaning out @ 90', drilling line stranded R.S.S.  
12-31-76 TD 110' hole caving in around rig.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: Ind B. Yates TITLE: Vice President DATE: 1-17-77

APPROVED BY: W. A. Gressett TITLE: SUPERVISOR, DISTRICT II DATE: JAN 19 1977

10. Signature of Approver, if any: