
Form 9-33! (May 1963)	Form approved. Budget Bureau No. 42-R1424.				
DEPART	MENT OF THE IN	TERIOR verse sid	instructions on re- le)	5. LEASE DESIGNATION AS	
	EOLOGICAL SURV			NM-10276	
	CES AND REPORT TO ME TO THE TOTAL TO THE TOTAL TO THE TOTAL TO THE TOTAL	RTS ON WELL r plug back to a differ r such proposals.)	.S ent reservoir.	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME
OIL GAS WELL OTHER		NM OID CONS.	CONTESTOR	7. UNIT AGREEMENT NAM	B
2. NAME OF OPERATOR McClellan Oil Corp	. /	Prawer DD	88210	8. FARM OR LEASE NAME Barbara "A"	Fed
3. ADDRESS OF OPERATOR Post Office Drawer	730, Roswell	, N. M.	RECEVED	9. WELL NO.	
4. LOCATION OF WELL (Report location of See also space 17 below.) At surface	early and in accordance w	ith any State requirem	nents.• NOV 1 2 1981		d
990' FNL & 660' FW	L		O. C. D. Antesia, conce	Sec. 10-T16	
14. PERMIT NO.	15. ELEVATIONS (Show wh	nether DF, RT, GR, etc.)	printed Marin Control	12. COUNTY OR PARISH	
	3708 G.L.			Eddy	N.M.
16. Check Ap	propriate Box To Indi	icate Nature of No	otice, Report, or C	Other Data	
NOTICE OF INTEN	TION 'TO:		SUBSEQU	ENT REPORT OF:	
	PULL OR ALTER CASING	-1 1	SHUT-OFF	REPAIRING WI	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
	MULTIPLE COMPLETE ABANDON*	l l	IRE TREATMENT	ABANDONMENT	
	ABANDON* CHANGE PLANS	(Other		1	
(Other)			Note: Report results completion or Recompl	of multiple completion of etion Report and Log form	n Well n.)
17. DESCRIBE PROPOSED OR COMPLETED OPP proposed work. If well is direction nent to this work.) *	RATIONS (Clearly state all mally drilled, give subsurfa	pertinent details, and ace locations and meas	give pertinent dates, sured and true vertica	including estimated date il depths for all markers	of starting any and zones perti
Propose to plug an	d abandoned t	his hole as	follows:	•	
Pull tubing. Pull Set cement plug fr	5-½" casing	@ free poir	nt.	orațione	
100' coment plug in	om 2300 -2400	etub of 5-3	esent perr	oracions.	

100' cement plug in and out of stub of 5-½" casing.
100' cement plug from 315'-415' in and out of 8-5/8" casing.
15 SX plug @ surface.

Place dry hole marker and restore surface to original condition.



OIL & GAS U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct SIGNED Mark McClellan	TITLE (zeologist	DATE _///2/3/	
(This space for Federal of PROWED APPROVADES: Sgd.) PETER W. CHESTER CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE	
NOV 1 0 1981 FOR JAMES A. GILLHAM DISTRICT SUPERVISOR	e Instructions on Reverse Side	A. T.	