

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

DATE SUBMIT IN TRI. ATE
(Other instructions on re-
verse side) 88210

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 2347

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT - RECEIVED" (See reverse side).)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P&A		2. NAME OF OPERATOR Yates Petroleum Corporation		3. ADDRESS OF OPERATOR 105 South 4th St., Artesia, NM 88210		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980 FNL & 1980 FEL, Sec. 35-T16S-R24E		5. LEASE DESIGNATION AND SERIAL NO. NM 2347		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3678' GR		16. COUNTY OR PARISH Eddy		17. STATE NM		8. AGREEMENT NAME		9. TERM OR LEASE NAME Carrisa HS Federal	
10. FIELD AND POOL, OR WILDCAT West Cottonwood Creek-Wolfcamp		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit G, Sec. 35-T16S-R24E		12. COUNTY OR PARISH Eddy		13. STATE NM		10. FIELD AND POOL, OR WILDCAT		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged well as follows:

Set CIBP at 4715'. WIH w/tubing to 4715' and tagged plug. Circulated hole w/mud. Spotted 10 sx Class "C" cement 4715-4568'. Shot pipe at 3045', could not pull pipe. Spotted 15 sx cement plug 3075-2858'. Shot casing at 2550', unable to pull. Shot casing at 2512'. Pulled 61 jts 4-1/2" casing. Spotted 35 sx Class "C" 2571-2402'. Tagged plug 2421'. Spotted 35 sx Class "C" plug at 1815-1600'. POOH to 913'. Spotted 50 sx cement plug. WOC. WIH to 913', no plug. Spot 90 sx cement at 913'. Tagged plug at 540'. Spotted 15 sx cement to bring up to 490'. Spotted 15 sx surface plug. Cut off wellhead. Installed regulation abandonment marker. Plugging completed 10-29-87.

ACCEPTED FOR RECORD

NOV 13 1987

SJS
CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Supervisor

DATE 10-30-87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



LTR



Job separation sheet

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P&A		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Yates Petroleum Corporation		8. FARM OR LEASE NAME Collins HS Federal	
3. ADDRESS OF OPERATOR 105 South 4th St., Artesia, NM 88210		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980 FNL & 1980 FEL, Sec. 35-T16S-R24E		10. FIELD AND POOL, OR WILDCAT West Cottonwood Creek-Wolfcamp	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3678' GR	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit G, Sec. 35-T16S-R24E		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Propose to plug and abandon well as follows:

Set CIBP at 4715' and cap w/35' cement. (Perforations from 4765-4837')

Freepoint 4 1/2" casing. Cut and pull 4 1/2" casing from approximately 50' above freepoint. Cement top at 4280' per temperature survey.

Spot following cement plugs through tubing:

50' in and out (100 feet total) of 4 1/2" casing stub. Tag plug.

3700-3800' across top of Abo

1730-1830' across top of Glorieta

816-916' across 8-5/8" casing shoe. Tag plug.

Set 15 sack plug at surface. Install regulation abandonment marker.

Use salt gel fluid between all plugs.

NOTIFY BLM, 24 hours before starting plugging procedures.

As per telecon w/ Ray Stahl; he will spot a 100' plug inside of 8 5/8" csg. to extend ±50' above Artesian water zone @ ±500'-750'. (SJS 5/29/87)

18. I hereby certify that the foregoing is true and correct

SIGNATURE <u>Juanita Doodler</u>	TITLE <u>Production Supervisor</u>	DATE <u>5-18-87</u>
(This space for Federal or State office use)		
APPROVED BY <u>Acting Area Manager</u>	TITLE <u></u>	DATE <u>5-29-87</u>
CONDITIONS OF APPROVAL, IF ANY:		

*See Instructions on Reverse Side