

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

AUG 21 '90

WELL API NO. 30-015-22203
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 647-320, 647-363, 647-368
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "E"
8. Well No. 372
9. Pool name or Wildcat EMPIRE ABO
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3681.1' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITS, OFFICE  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator ARCO OIL AND GAS COMPANY /
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240	4. Well Location Unit Letter <u>D</u> : <u>100</u> Feet From The <u>NORTH</u> Line and <u>1291.14</u> Feet From The <u>WEST</u> Line Section <u>35</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>EDDY</u> County <u></u>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: TEMPORARILY ABANDON <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN

TD 6383'; PBD 6335'; Perfs: 6262-6270'

8/8/90 MIRU DDPU Well dead. N/D W/H N/U BOP. Unset pkr. POH w/tbg, Kobe cavity, and pkr. RIH w/CIBP, running tool, and tbg. Set CIBP. POH w/l jt tbg. R/U pump truck. Circulate well w/8.6# brine w/WT-675 chemical. SDON.

8/9/90 R.O. Well dead. R/U pump truck. Load well. Pressure up to 500#. Held for 15 mins. (Chart attached.) POH w/tbg and CIBP running tool. Layed tbg down in singles. N/D BOP N/U W/H. Left 1 jt tbg on W/H flange. RDCL. CIBP set @ 6229.72'. Pressure test witnessed by Mike Stubblefield-NMOCD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Administrative Supervisor DATE 8/20/90  
TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-3551

(This space for State Use)

APPROVED BY Angelo Williams TITLE OIL AND GAS SUPERVISOR DATE 8/24/90  
CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary  
Abandonment Expires 8/9/95

