PO. Drow DD, Amada, NM 8210 Dataset 10, NM Marked 0 1904 2000 PTHECT III Statuse NA DOD Bio Brace Rd, Assee, NM 8740 Sauc Cd & Gus Lesse NA SUNDARY MOTICES AND REPORTS ON WELLS Sauc Cd & Gus Lesse NA (DO NOT USE THIS FORM FOR PROPOSALS TO DOPLLO R TO PEPENT FREERWORM, USE "APPLICATION FOR PEPMET" Name of Usit Agreement Name 1. Type of Well: Gas Mitchell IN 2. Mana of Operator Statuse Name or Usit Agreement Name Name of Usit Agreement Name 1. Type of Well: Gas Mitchell IN Lesse Name or Usit Agreement Name 2. Addees of Operator Addees of Operator Name of Usit Agreement Name 24 3. Addees of Operator Addees of Operator South for S	to Appropriate District Office	State of New M Energy, Minerals and Natural R		Form C-103 Revised 1-1-89
DSTECTION Samua Fe, New Mexico 87504-2088 30-013-222422 DSTECTION Subcord DA, Asse, NM 87410 5. Indices Type of Laser System Classes Type	DISTRICT I			WELL API NO.
Idea Bis Binder Rd, Asse, NM F7410 6 Sub CU & Gus Lase No. SUNDRY NOTICES AND REPORTS ON WELLS: (CONNOT USE THIS FORM OR PROPONDALS TO DAML OR TO DEFEN OR PLUD BACK TO A 7. Lase Name or Unit Agreement Name 1. Type of Wilt: Gas. Gas. Mitchell IN 2. Name of Operator SWD: Mitchell IN 2. Addres of Operator SWD: Mitchell IN 3. Addres of Operator SWD: SWD: 2 3. Addres of Operator SWD: SWD: County 4. Well Cosilo South 4th 5t., Artesia, NM 88210 SWD: Peer From The Edgy 3. Addres of Operator 17.5 Swattriantor of Notice, Report, or Other Data SWD: SWD: County 4. Well Cosilo Use ND ABANDON REMEDAL WORK ALTERING CASING County SUBSEQUENT REPORTOF: Freedore Noroscill Comprise David Addres Addres Addres Addres Edge of Operator County County SWD: County County				5. Indicate Type of Lease
(DO NOT USE THIS FORM FOR PROPOSALS TO BILL OR TO DEEPEN OF PLUG BACK TO A 7. Lake Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO APPLICATION OF REMATT 7. Lake Name or Unit Agreement Name (Type of Weil				
DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROFORALS. 1. Type of Well: Support 2. Name of Openator 2. Name of Openator 3. Well Kall Control (Control (SUNDRY NOT	ICES AND REPORTS ON WE	LLS	
OK ONE SWD Mitchell IN 2 None of Openace Auto of Openace 8 Well No. 3 Addee of Openace AUto 15 (595) 9. Poil sum or Wilded 105 South 4th St., Artesia, NM 88210 Suff. 9. Poil sum or Wilded 105 South 4th St., Artesia, NM 88210 Suff. 9. Poil sum or Wilded 105 South 4th St., Artesia, NM 88210 Suff. Suff. 9. Poil sum or Wilded 105 South 4th St., Artesia, NM 88210 Suff. Suff. Suff. Suff. Sector 23 Tomakip 175 Bage 25E NMTM Eddy Coury 101 South 4th St., Artesia, NM 84210 Suff. Suff. Coury Suff. Coury 110 South 4th St., Artesia, NM 88210 Tomakip 175 Bage 25E NMTM Eddy Coury 111 State Coury 3476' GR Suff. Suff. Coury Suff. 111 Unc All FENCHAL WORK Putenacity Nonk Keff. Putenacity Nonk Suff. Artening Coury Coury Coury Suff. Suff. Coury Suff. Coury Suff. Suff. Suff. Suff. Coury Suff. Coury Suff.	DIFFERENT RESE	RVOIR. USE "APPLICATION FOR PE	N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
YATES PETROLEUM CORPORATION 2 Addeed of Operator AUG 1 5 1995 9. Pod mame or Wilded 103 South 4th St., Artesia, NM 88210 SWD - Devonian 4 Wall Lossica SwD - Devonian 660° 4 Wall Lossica SwD - Devonian 660° 23 Township 178 Rueg 25E NMPM Eddy County 10 South Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: EMPORARIY ABANDON CHANGE PLANS CCMMENCE DRULING OPNS. PLUG AND ABANDONMENT ULI OR ALTER CASING CAMINE CENTRY OF CASING TEST AND CEMENT JOB Porter Clean fill out & fe-acidize existing K VUL OR ALTER CASING CHANGE PLANS Comment dust, iciding attinated dust of saning any project work) SEE RUE 103. Sector at 8790'. TOOH with 2-7/8" plastic coated tubing and packer. TIH work) SEE RUE 103. Sector at 8790'. TOOH with 2-7/8" plastic coated tubing and packer. TIH water. Tested casing to 1000 psi for 15 minutes. Be-796 - Moved in and rigged up pulling unit. Nippled down wellhead and installed BOP. Unset Uni VI packer at 8790'. TOOH with 2-7/8" plastic coated tubing and packer. TIH water. Tested casing to 1000 psi for	OIL CAS WELL C	OTHER	CEVEN	Mitchell IN
105 South 4th St., Artesia, NM 88210 SWD - Devonian 4 Well Leasure 1:2000 SWD - Devonian 4 Well Leasure 1:2000 Feet From The South George 25E NMTM Edst List 4 Well Leasure 1:3 23 Township 175 Range 25E NMTM Eddy County 10 Elevation (Show whether DF, RED, RT, GR, act) 3476' GR GR County County County 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: EMPORARILY ABANDON CHANGE PLANS COMMENCE DFULING OPNS. PLUG AND ABANDONINENT ULI OR ALTER CASING CHANGE PLANS COMMENCE DFULING OPNS. PLUG AND ABANDONINENT VUL OR ALTER CASING CHANGE PLANS COMMENCE DFULING OPNS. PLUG AND ABANDONINENT VUL OR ALTER CASING CHANGE PLANS Content of the packer and 2-7/8" Stating and packer. TH VUL OR ALTER CASING Check Paprovide of Completed Operations (Clearly stat all perions dual, and give privent dual, iclusing estimated dual of stating and packer. TH VUL OR ALTER CASING Check and 77/8" Jos		L	f host of	8. Well No.
4 Well Location Internet Interne Internet In	•	, NM 88210	UG 1 5 1996	
Sector 23 Township 175 Range 25E NMTM Eddy County 10. Elevation (Abov which a DF, REB, RT, GR, acc) 3476' GR 3476' GR 3476' GR General Control (Control (Cont)))))))))))))))))))))) </td <td>4. Well Location</td> <td>·</td> <td>CONL DW</td> <td></td>	4. Well Location	·	CONL DW	
10. Elevation (Show view DF, RED, RT, GR, etc.) 3476' GR 3476' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: ERFORM REMEDIAL WORK PLUG AND ABANDON Change PLANS SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING CHANGE PLANS COMMENCE ORILLING OPNS. PLUG AND ABANDON CHANGE PLANS Change Transmission Commence Originate duals, and give provised duals of saming any proposed World SEE RULE 1003. Clearn fill out & re-acidize existing K Derive Proposed or Completed Operations (Clearly state all perivers) duals, and give provised duals, and give provised duals of saming any proposed World SEE RULE 1003. Refer at 8790'. TOOH with 2-7/8" plastic coated tubing and packer. TIH w/RBP, packer and 2-7/8" J-55 work string. Set RBP at 8742'. Loaded casing with fresh water. Tested casing to 1000 psi for 15 minutes. 8-796 - TOOH with tubing, packer and RBP. TIH with bailer, port sub and 2-7/8" tubing. 718' tubing, backer and 879-9362' with 10000 gallons 202 iron control acid and bailer. 8-96 - Acidized perforations 8879-9362' with 10000 gallons 202 iron control acid and bails sealers. Bled well down. TOOH and lay down work string and packer. 8-996 - Tested in hole with nickel	Unit Letter::20.3	10 Feet From The SOULTH	Line and660	Feet From The East Line
3476' GR NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE OFILLING OPNS. PLUG AND ABANDONMENT COMMENCE OFILLING OPNS. PLUG AND ABANDON COMMENT COLSPANDON COMMENT COMMENT <td>Section 23</td> <td>Township 17S R</td> <td>ange 25E I</td> <td>MPM Eddy County</td>	Section 23	Township 17S R	ange 25E I	MPM Eddy County
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VULL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VUL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VUL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VUL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VUL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VUL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VUL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VUL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VUL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VUL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VIL OR ALTER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT VIL OR ALTER CASING COMMENT CLASSE O		///////	-	
ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ULL OR ALTER CASING CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT OTHER: OTHER: Clean fill out & re-acidize existing K OTHER: OTHER: Clean fill out & re-acidize existing K 12. Describe Proposed or Completed Operations (Clearly state all perintensi data); and give perintensi data; including estimated data of starting any proposed 86-6.96 Moved in and rigged up pulling unit. Nippled down wellhead and installed BOP. Unset Uni VI packer at 8790'. TOOH with 2-7/8" plastic coated tubing and packer. TIH wikBP, packer and 2-7/8" J-55 work string. Set RBP at 87/42'. Loaded casing with fresh water. water. Tested casing to 1000 psi for 15 minutes. Bled pressure off. Pressured up down 2-7/8" tubing, packer and RBP. down 2-7/8" tubing, backer and RBP. TIH with bailer, port sub and 2-7/8" tubing. Set packer at 8770'. 8-8-96 - Acidized perforations 8879-9362' with 10000 gallons 20% iron control acid and bail sealers. Bled well down. TOOH and lay down work string and packer. 8-9-96 - Tested in hole with nickel plated Uni VI packer and 2-7/8" plastic coated tubing. Loade			Nature of Notice, Re	port, or Other Data
EMPOPARILY ABANDON CHANGE PLANS CAMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ULL OR ALTER CASING CAMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB COMMENT STRAIG STRUCT IN SUBJECT OF STATUS STATU	NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF
ULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: Clean fill out & re-acidize existing I2 Describe Proposed or Completed Operations (Clearly state all periment datals, including estimated data of starting any proposed work) SEE RULE 1103. 8-6-96 - Moved in and rigged up pulling unit. Nippled down wellhead and installed BOP. Unset Uni VI packer at 8790'. TOOH with 2-7/8" plastic coated tubing and packer. TIH w/RBP, packer and 2-7/8" J-55 work string. Set RBP at 8742'. Loaded casing with fresh water. Tested casing to 1000 psi for 15 minutes. 8-70-96 - TOOH with tubing, packer and RBP. TIH with bailer, port sub and 2-7/8" tubing. Tagged fill at 9364'. Bailed casing out to 9412'. TOOH with tubing, port sub and bailer. THH with packer and 2-7/8" tubing. Set packer at 8770'. 8-8-96 - Acidized perforations 8879-9362' with 10000 gallons 20% iron control acid and bail sealers. Bled well down. TOOH and lay down work string and packer. Set packer at 8793'. 8-9-96 - Tested in hole with nickel plated Uni VI packer and 2-7/8" plastic coated tubing. Set packer at 8793'. 8-9-96 - Tested in hole with packer fluid. Removed BOP and nippled up wellhead. 8-9-96 - Tested in hole wi			REMEDIAL WORK	
OTHER: OTHER: Clean fill out & re-acidize existing [X] perfs 12. Describe Proposed or Completed Operations (Clearly state all perioses details, and give perioses data), and give perioses data, including estimated date of starting any proposed 8-6-96 - Moved in and rigged up pulling unit. Nippled down wellhead and installed BOP. Unset Uni VI packer at 8790'. TOOH with 2-7/8" plastic coated tubing and packer. TIH w/RBP, packer and 2-7/8" J-55 work string. Set RBP at 8742'. Loaded casing with fresh water. Tested casing to 1000 psi for 15 minutes. Bled pressure off. Pressured up down 2-7/8" tubing with packer unset to 1000 psi for 15 minutes. 8-7-96 - TOOH with tubing, packer and RBP. TIH with bailer, port sub and 2-7/8" tubing. Tagged fill at 9364'. Bailed casing out to 9412'. TOOH with tubing, port sub and bailer. TIH with packer and 2-7/8" tubing. Set packer at 8770'. 8-8-96 - Acidized perforations 8879-9362' with 10000 gailons 20% iron control acid and ball sealers. Bled well down. TOOH and lay down work string and packer. 8-9-96 - Tested in hole with nickel plated Uni VI packer and 2-7/8" plastic coated tubing. Loaded annulus with packer fluid. Removed BOP and nippled up wellhead. Set packer at 8793'. Tested annulus to 900 psi for 30 minutes. OCD-Artesia was notified but did not witness. Released well to production to return to injection. Iberty Configurations Released well to production to return to injection. Iberty centry that for informations above is true and complete to the best of my trowledge and ball. Image of futures. Ruesty Klein The packer at 8793'. Tested annulus to 900 psi for 30 minutes. OCD-Artesia was notified but did not witness. Re		CHANGE PLANS	COMMENCE DRILLING	OPNS.
12. Describe Proposed or Completed Operations (Clearly state all periment datails, and give periment datas, including estimated date of starting any proposed work) SEE RULE 1103. 8-6-96 - Moved in and rigged up pulling unit. Nippled down wellhead and installed BOP. Unset Uni VI packer at 8790'. TOOH with 2-7/8" plastic coated tubing and packer. TIH w/RBP, packer and 2-7/8" J-55 work string. Set RBP at 8742'. Loaded casing with fresh water. Tested casing to 1000 psi for 15 minutes. Bled pressure off. Pressured up down 2-7/8" tubing, packer and RBP. TIH with bailer, port sub and 2-7/8" tubing. Tagged fill at 9364'. Bailed casing out to 9412'. TOOH with tubing, port sub and bailer. TIH with packer and 2-7/8" tubing. Set packer at 8770'. 8-8-96 - Acidized perforations 8679-9362' with 10000 gallons 20% iron control acid and bail sealers. Bled well down. TOOH and lay down work string and packer. 8-96 - Tested in hole with nickel plated Uni VI packer and 2-7/8" plastic coated tubing. Loaded annulus with packer fluid. Removed BOP and nippled up wellhead. Set packer at 8793'. Tested annulus to 900 psi for 30 minutes. OCD-Artesia was notified but did not witness. Released well to production to return to injection. 12. Heredy cartify the Information above is true and complete to the best of my trowkedge and beld. 300 MATURE MATURE MATURE OPERATIONS TEChnician DATE Aug. 13, 1996 TYPE OR FRIGHT NAME Operations Technician DATE Aug. 13, 1996 (This space for State Une) Operations Technician DATE Aug. 13, 1996 (This space for State Une) Operations Technician DATE Aug. 13, 1996	ULL OR ALTER CASING		CASING TEST AND CE	
work) SEE RULE 1103. 8-6-96 - Moved in and rigged up pulling unit. Nippled down wellhead and installed BOP. Unset Uni VI packer at 8790'. TOOH with 2-7/8" plastic coated tubing and packer. TIH w/RBP, packer and 2-7/8" J-55 work string. Set RBP at 8742'. Loaded casing with fresh water. Tested casing to 1000 psi for 15 minutes. Bled pressure off. Pressured up down 2-7/8" tubing with packer unset to 1000 psi for 15 minutes. 8-7-96 - TOOH with tubing, packer and RBP. TIH with bailer, port sub and 2-7/8" tubing. Tagged fill at 9364'. Bailed casing out to 9412'. TOOH with tubing, port sub and bailer. TIH with packer and 2-7/8" tubing. Set packer at 8770'. 8-8-96 - Acidized perforations 8879-9362' with 10000 gallons 20% iron control acid and bail sealers. Bled well down. TOOH and lay down work string and packer. 8-9-96 - Tested in hole with nickel plated Uni VI packer and 2-7/8" plastic coated tubing. Loaded annulus with packer fluid. Removed BOP and nippled up wellhead. Set packer at 8793'. Tested annulus to 900 psi for 30 minutes. OCD-Artesia was notified but did not witness. Released well to production to return to injection. Iberty certify the fulformatics dows is instand complets to the best of my knowledge and beld. SHOMATURE Mug 2 6 1996 THE AUG. 2 6 1996 Chie space for State Ueo) ORIGNAL SIGNED BY TIM W. GUM DISTRICT II SUPERVISOR AUG 2 6 1996	DTHER:	[]		l out & re-acidize existing 🛛
8-6-96 - Moved in and rigged up pulling unit. Nippled down wellhead and installed BOP. Unset Uni VI packer at 8790'. TOOH with 2-7/8" plastic coated tubing and packer. TIH w/RBP, packer and 2-7/8" J-55 work string. Set RBP at 8742'. Loaded casing with fresh water. Tested casing to 1000 psi for 15 minutes. Bled pressure off. Pressured up down 2-7/8" tubing with packer unset to 1000 psi for 15 minutes. 8-7-96 - TOOH with tubing, packer and RBP. TIH with bailer, port sub and 2-7/8" tubing. Tagged fill at 9364'. Bailed casing out to 9412'. TOOH with tubing, port sub and bailer. TIH with packer and 2-7/8" tubing. Set packer at 8770'. 8-8-96 - Acidized perforations 8879-9362' with 10000 gallons 20% iron control acid and ball sealers. Bled well down. TOOH and lay down work string and packer. 8-9-96 - Tested in hole with nickel plated Uni VI packer and 2-7/8" plastic coated tubing. Loaded annulus with packer fluid. Removed BOP and nippled up wellhead. Set packer at 8793'. Tested annulus to 900 psi for 30 minutes. OCD-Artesia was notified but did not witness. Released well to production to return to injection. I berdy outly the Informatic above is the test of my trowkedge and belief. MONATURE Must Klein must be to a for y trowkedge and belief. MUG 2 6 1996 (This space for State Use) ORIGNAL SIGNED BY TIM W. GUM DISTRICT II SUPERVISOR		ations (Clearly state all pertinent details, a	nd give pertinent dates, includ	ing estimated date of starting any proposed
down 2-7/8" tubing with packer unset to 1000 psi for 15 minutes. 8-7-96 - TOOH with tubing, packer and RBP. TIH with bailer, port sub and 2-7/8" tubing. Tagged fill at 9364'. Bailed casing out to 9412'. TOOH with tubing, port sub and bailer. TIH with packer and 2-7/8" tubing. Set packer at 8770'. 8-8-96 - Acidized perforations 8879-9362' with 10000 gallons 20% iron control acid and bail sealers. Bled well down. TOOH and lay down work string and packer. 8-9-96 - Tested in hole with nickel plated Uni VI packer and 2-7/8" plastic coated tubing. Loaded annulus with packer fluid. Removed BOP and nippled up wellhead. Set packer at 8793'. Tested annulus to 900 psi for 30 minutes. OCD-Artesia was notified but did not witness. Released well to production to return to injection. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SHONATURE TYPE OR FRINT NAME Rusty Klein THE OPERATIONS TECHNICIAN ORIGINAL SIGNED BY TIM W. GUM DISTRICT II SUPERVISOR AUG 2 6 1996	8-6-96 - Moved in and Unset Uni VI packer a w/RBP, packer and 2-7	t 8790'. TOOH with 2- /8" J-55 work string.	7/8" plastic coa Set RBP at 8742	ted tubing and packer. TIH '. Loaded casing with fresh
Tagged fill at 9364'. Bailed casing out to 9412'. TOOH with tubing, port sub and bailer. TIH with packer and 2-7/8" tubing. Set packer at 8770'. 8-8-96 - Acidized perforations 8879-9362' with 10000 gallons 20% iron control acid and ball sealers. Bled well down. TOOH and lay down work string and packer. 8-9-96 - Tested in hole with nickel plated Uni VI packer and 2-7/8" plastic coated tubing. Loaded annulus with packer fluid. Removed BOP and nippled up wellhead. Set packer at 8793'. Tested annulus to 900 psi for 30 minutes. OCD-Artesia was notified but did not witness. Released well to production to return to injection. I hereby certify that the informatice above is true and complete to the best of my knowledge and belief. SNONATURE Musty Klein Must SignED BY TIM W. GUM Chis space for State Une) ORIGNAL SIGNED BY TIM W. GUM DISTRICT II SUPERVISOR	down 2-7/8" tubing wi 8-7-96 - TOOH with tu	th packer unset to 100 bing, packer and RBP.	0 psi for 15 min TIH with bailer	utes. , port sub and 2-7/8" tubing.
8-8-96 - Acidized perforations 8879-9362' with 10000 gallons 20% iron control acid and ball sealers. Bled well down. TOOH and lay down work string and packer. 8-9-96 - Tested in hole with nickel plated Uni VI packer and 2-7/8" plastic coated tubing. Loaded annulus with packer fluid. Removed BOP and nippled up wellhead. Set packer at 8793'. Tested annulus to 900 psi for 30 minutes. OCD-Artesia was notified but did not witness. Released well to production to return to injection. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKONATURE Aug. 13, 1996 TYPE OR PRINT NAME Rusty Klein THE Operations Technician DATE Aug. 13, 1996 TYPE OR FRINT NAME Rusty Klein AUG. 26 1996	Tagged fill at 9364'.	Bailed casing out to	94121 TOOH wi	th tubing nort sub and bailer
8-9-96 - Tested in hole with nickel plated Uni VI packer and 2-7/8" plastic coated tubing. Loaded annulus with packer fluid. Removed BOP and nippled up wellhead. Set packer at 8793'. Tested annulus to 900 psi for 30 minutes. OCD-Artesia was notified but did not witness. Released well to production to return to injection. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SHONATURE	TIH with packer and 2	-7/8" tubing. Set pac	ker at 8770'.	
packer at 8793'. Tested annulus to 900 psi for 30 minutes. OCD-Artesia was notified but did not witness. Released well to production to return to injection. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SHONATURE	8-8-96 - Acidized per ball sealers. Bled w	forations 8879-9362' w ell down. TOOH and la	ker at 8770'. ith 10000 gallon y down work stri	s 20% iron control acid and ng and packer.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	8-8-96 - Acidized per ball sealers. Bled w 8-9-96 - Tested in ho	forations 8879-9362' w ell down. TOOH and la le with nickel plated	ker at 8770'. ith 10000 gallon y down work stri Uni VI packer an	s 20% iron control acid and ng and packer. d 2-7/8" plastic coated
SHONATURE KIEIN Operations Technician DATE Aug. 13. 1996 TYPE OR FRENT NAME RUSTY KIEIN DATE Aug. 13. 1996 THE PHONE NO. 505/748-1 (This space for State Use) ORIGINAL SIGNED BY TIM W. GUM DISTRICT II SUPERVISOR	8-8-96 - Acidized per ball sealers. Bled w 8-9-96 - Tested in ho tubing. Loaded annul packer at 8793'. Tes	forations 8879-9362' w ell down. TOOH and la le with nickel plated us with packer fluid. ted annulus to 900 psi	ker at 8770'. ith 10000 gallon y down work stri Uni VI packer an Removed BOP and for 30 minutes.	s 20% iron control acid and ng and packer. d 2-7/8" plastic coated nippled up wellhead. Set OCD-Artesia was notified
(This space for State Use) ORIGINAL SIGNED BY TIM W. GUM DISTRICT II SUPERVISOR AUG 2 6 1996	8-8-96 - Acidized per ball sealers. Bled w 8-9-96 - Tested in ho tubing. Loaded annul packer at 8793'. Tes but did not witness.	forations 8879-9362' w ell down. TOOH and la le with nickel plated us with packer fluid. ted annulus to 900 psi Released well to prod	ker at 8770'. ith 10000 gallon y down work stri Uni VI packer an Removed BOP and for 30 minutes. uction to return	s 20% iron control acid and ng and packer. d 2-7/8" plastic coated nippled up wellhead. Set OCD-Artesia was notified
DISTRICT II SUPERVISOR AUG 2 6 1950	8-8-96 - Acidized per ball sealers. Bled w 8-9-96 - Tested in ho tubing. Loaded annul packer at 8793'. Tes but did not witness.	forations 8879-9362' w ell down. TOOH and la le with nickel plated us with packer fluid. ted annulus to 900 psi Released well to prod	ker at 8770'. ith 10000 gallon y down work stri Uni VI packer an Removed BOP and for 30 minutes. uction to return	s 20% iron control acid and ng and packer. d 2-7/8" plastic coated nippled up wellhead. Set OCD-Artesia was notified to injection.
	8-8-96 - Acidized per ball sealers. Bled w 8-9-96 - Tested in ho tubing. Loaded annul packer at 8793'. Tes but did not witness. I hereby certify that the information above is in SIGNATURE Harty Kled	forations 8879-9362' w ell down. TOOH and la le with nickel plated us with packer fluid. ted annulus to 900 psi Released well to prod gand complete to the best of my knowledge and	ker at 8770'. ith 10000 gallon y down work stri Uni VI packer an Removed BOP and for 30 minutes. uction to return	s 20% iron control acid and ng and packer. d 2-7/8" plastic coated nippled up wellhead. Set OCD-Artesia was notified to injection. cchnician <u>Aug. 13, 1996</u>
	8-8-96 - Acidized per ball sealers. Bled w 8-9-96 - Tested in ho tubing. Loaded annul packer at 8793'. Tes but did not witness. I hereby certify that the information above is the such at the second	forations 8879-9362' w ell down. TOOH and la le with nickel plated us with packer fluid. ted annulus to 900 psi Released well to prod gand complete to the best of my knowledge and us to the b	ker at 8770'. ith 10000 gallon y down work stri Uni VI packer an Removed BOP and for 30 minutes. uction to return	s 20% iron control acid and ng and packer. d 2-7/8" plastic coated nippled up wellhead. Set OCD-Artesia was notified to injection. chnician DATE Aug. 13, 1996 TELEPHONE NO. 505/748-1

!