

NO. OF COPIES RECEIVED

DISTRIBUTION

SANTA FE

FILE

U.S.G.S.

LAND OFFICE

OPERATOR

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JAN 13 '89

O. C. D.
ARTESIA, OFFICEForm C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease

State ☐Farm ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)1. OIL WELL ☐ GAS WELL ☒ OTHER-

2. Name of Operator

BEARD OIL COMPANY (405) 842-2333 ✓

3. Address of Operator

Enterprise Plaza, Ste. 200, 5600 N. May Ave., Oklahoma City, OK 73112

4. Location of Well

UNIT LETTER K 1983 FEET FROM THE South LINE AND 1992 FEET FROMTHE West LINE, SECTION 8 TOWNSHIP 17 South RANGE 24 East NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

HAGSTROM

9. Well No.

1

10. Field Hagstrom, or WildcatEast Hope ATOICA

15. Elevation (Show whether DF, RT, GR, etc.)

3818' KB

12. County

Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐TEMPORARILY ABANDON ☐PULL OR ALTER CASING ☐PLUG AND ABANDON ☒CHANGE PLANS ☐OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐COMMENCE DRILLING OPNS. ☐CASING TEST AND CEMENT JOBS ☐OTHER ☐ALTERING CASING ☐PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Perforations 7022-34'. Packer @ 6975'. Pull packer; spot 25 sx or 100' of cement across Atoka (6963') from 7010-6910'. If unable to pull packer, cut off tubing at packer; spot 25 sx of cement on top of packer. WOC. Tag either plug. Displace hole with drilling mud.

25 sx or 100' of cement across top of Pennsylvania @ 5920-5820'

25 sx or 100' of cement across top of Wolfcamp @ 4750-4650'

Pull casing - cut off @ 3700'

25 sx or 100' of cement in top of casing and across Abo @ 3700-3600'

25 sx or 100' of cement below Glorieta (1670') 3040-2940'

25 sx or 100' across top of Glorieta 1720-1620'

100' cement plug in and out of bottom of surface casing (1107') 1157-1057'

Surface plug 250' to surface.

Per telephone conversation with Mike Williams, New Mexico Oil Conservation Commission 1/6/89.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE Assistant Operations Manager

DATE 1-6-89

APPROVED BY

TITLE

DATE

JAN 16 1989

CONDITIONS OF APPROVAL, IF ANY:

Plugging