Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

HATTI ARKANO		
WELL API NO.	. 1 -	
30-015-224	+15	
5. Indicate Type of L	case	
	STATE	FEE 📙
6. State Oil & Gas Le	ase No.	

DISTRICT II		Canta Ee New	Santa Fe, New Mexico 87504 2088 ED		30-013-22413		
P.O. Drawer DD, An	tesis, NM 88210	Santa 1 e, 14e v,			5. Indicate Type of	Lease V	
DISTRICT III 1000 Rio Brazos Rd.	Amer NR 97410		J.	UN 1 8 19 91	6. State Oil & Gas		FEE
1000 NO BIRZOS NO.	, A200, 1401 07410			O. C. D.	a sale of a G	resse No.	
		ES AND REPORTS		RTESIA, OFFICE			
		POSALS TO DRILL OR TO VOIR. USE "APPLICATIO			7. Lease Name or	Unit Agreement Name	
		101) FOR SUCH PROPOS					
1. Type of Well:	043 —				TIME I	DO INITE HOLL	
MET X	MET [OTHER			EMPIRE A	ABO UNIT "G"	··
2. Name of Operato		NTS7			8. Well No. 323		
3 Address of Opera	AND GAS COMPA	IN I			9. Pool name or V	Vildcat	
	HOBBS, NEW M	EXICO 88240			EMPIRE A		
4. Well Location							
Unit Letter	:1500	Feet From The SO	UTH	Line and	Feet From	The EAST	Line
	33	Township 17S	Range	28E	NMPM EDI)V	•
Section			ow whether DF, RI		NWIPM EDI	<u> </u>	County ///////
		3663.91	GR				
11.	Check A	ppropriate Box to I	ndicate Natu	re of Notice, Re	port, or Other	Data	
NO	OTICE OF INTI	ENTION TO:		SUB	SEQUENT R	EPORT OF:	
PERFORM REMEDI	IAI WORK	PLUG AND ABANDO	N BEL	ÆDIAL WORK		ALTERING CASING	Г
	_						
TEMPORARILY ABA	ANDON	CHANGE PLANS		MENCE DRILLING	OPNS.	PLUG AND ABANDON	IMENT L
PULL OR ALTER CA	asing 🗌		CAS	SING TEST AND CE	MENT JOB		
OTHER:			_ 🗌 отн	ER: TEMPORARI	LY ABANDON		X
10.0	A Completed Occasi	Miles and a sill marries a	e desaile and aim				
work) SEE RUL		ons (Clearly state all pertinen	i aeiaus, ana give	perimeni adies, inciud	ung estimated date of	starting any proposed	
TA & HOLD	WELL BORE FO	R FIELD BLOW DO	WN				
TD 62101.	DEDEC: 6107_	6219' (OPEN HOL	F)				
•					011 ED TD 015		
6/11/91		ND WH. NU BO					
6/13/91	R.O. RIH w/	4-3/4" BIT, $5-1$	/2" SCRAPP	ER, AND TBG.	POH w/TBC	G, SCRAPPER, A	7ND
		ER AND BIT PULL			RU HOT OII	L UNIT. PUMP	75
	·	S P-570 CHEMICA					
6/14/91	R.O. RIH w/	'4-3/4", 5-1/2"	SCRAPPER,	AND TBG. PO	OH w/TBG, SO	CRAPPER AND BI	IT.
		N ON SCRAPPER APOH w/1 JT TBG.					
		N. PRESSURE UP					
	LAYING DOWN	IN SINGLES. ND	BOP. CIE	SP SET @ 6181	1.67'. PRES	SSURE TEST CHA	ART
_		EST WITNESSED B		LIAMS, NMOCI).		
I hereby certify that the	information above is true a	and complete to the best of my kn				c /17 /01	
	information above is true a			ministrative	e Superviso	r DATE 6/17/91	
SIGNATURE	and g	hu		ministrative	Supervison		
		hu		ministrative	e Superviso	TELEPHONE NO. 392	
SIGNATURE	James D. C	hu	me Ad	ministrative	e Superviso		2-1600

CONDITIONS OF AFFROVAL, IF ANY:

This Approval of Temporary Abandonment Expires