

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.

Santa Fe, NM 87505

WELL API NO. 30-015-22592
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Empire Abo Unit "G"
8. Well No. 313
9. Pool name or Wildcat Empire Abo

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator ARCO Permian	
3. Address of Operator P.O. Box 1089 Eunice, NM 88231	
4. Well Location Unit Letter J : 2000 Feet From The S Line and 2450 Feet From The E Line Section 33 Township 17S Range 28E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3662.5' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6360' CIBP: 5950' PERFS: 5750-5842'

07/22/97: RIH w/5-1/2" csg scraper & bit to PBTD. POOH w/scraper & bit. RIH w/model "R" pkr to 6152'. Test csg to 500# psi, held good. Release pkr.
07/23/97: RIH w/CR, set @ 6155'. Pmp 30 bbls 8.6# bring thru retainer to set.
07/24/97: Squeeze lower abo perfs @ 6200-6220' w/75 sx class "C" neat. Sting out of retainer and reverse out. POOH w/tbg & setting tool.
07/25/97: Perf 5980-6034' w/4" guns, 108 holes. RIH w/pkr to 5934' & set. Swab down. Acidize perfs w/2000 gals 15% NEFE and 125 ball sealers.
07/29/97: Release pkr, POOH w/pkr & tbg. Set CIBP @ 5950'. Perf 5650-5842', 152 holes.
07/30/97: RIH w/pkr & tbg set pkr @ 5934'. Test CIBP, held good. Release pkr pull to 5691', set pkr. Acidize w/2000 gals 15% NEFE w/150 ball seals. RIH w/tbg. Set @ 5867'. SN @ 5831'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Assistant DATE 04/13/99

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use) **ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR**

APPROVED BY B62 TITLE _____ DATE 4-21-99

CONDITIONS OF APPROVAL, IF ANY: