

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

CISF
9

DISTRICT I
P.O. Box 1980 Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer 105, Artesia NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-015-22630

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-2071-25

7. Lease Name or Unit Agreement Name
EMPIRE ABO UNIT "F"

8. Well No.
362

9. Pool name or Wildcat
EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
BP America Production Company

3. Address of Operator
P.O. Box 1089 Eunice, NM 88231

4. Well Location
Unit Letter H : 1850 Feet From The N Line and 350 Feet From The E Line

Section 34 Township 17S Range 28E NMPM EDDY County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3674.6' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Workover ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6378' PBD: 6014' CIBP PERFS: 5829-5970'

07.29.02: MIRUPU. NDWH. NUBOP.

07.30.02: PU bit, scraper, & tbq. Test tbq in hole to 5000# psi below slips. Tag @ 6000'.

07.31.02: RU & dump 10' cmt on CIBP. Perf w/2 JSPF 5829-34', 5851-58', 5864-5925', 5937-5940', 5956-58', 5956-58', 5962-70'. 184 holes total. TIH w/treating pkr to 5975'.

08.01.02: Pmp 500 gals 7.5% HCL to pickle tbq. Wait 30 mins. Swab back acid. Fish SV. Spot 150 gals 15% HCL w/additives. PU & set pkr @ 5728'. Pmp 4600 gals 15% HCL w/additives & 275 ball sealers.

08.02.02: RIs pkr. Well started flowing back. (OVER)

I hereby certify that the information above is true and complete, to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Administrative Assistant DATE 09.23.02

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

Accepted for record - NMOC

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Empire Abo Unit F-362

30.015.22630

Workover Procedure continued:

08.05.02: TOH w/pkr. TIH w/bailer & clean out ball sealers. TOH.

08.06.02: TIH w/tbg. NDBOP. Set TAC. NUWH. Swab well.

08.12.02: Well SI waiting on electrical connection.