NO. OF COPIES RECEIVED	Form C-103
DISTRIBUTION	Supersedes Old C+102 and C-103
SANTA FE / NEW MEXICO OIL CONSERVANOE COMMISSION E D	Effective 1-1-65
FILE //	
U.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE NOV 3 0 1978	State XX Fcc
OPERATOR /	5. State Oil & Gas Lease No.
G. C. C.	OG 181
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DHILL OR TO DEEPEN OR PLUG RACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT	
1.	7. Unit Agreement Name
OIL GAS WELL OTHER-	· · · ·
2. Name of Operator	8. Farm or Lease Name
Yates Petroleum Corporation V	Lucas Store JZ State
3. Address of Operator	9. Well No. COM
207 South Fourth Street - Artesia, NM 88210	1 1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>E 1980</u> FEET FROM THE NORTH LINE AND 860 FEET FROM	Und. Empire Penn
•	
THE West LINE, SECTION 23 TOWNSHIP 175 RANGE 28E NMPM.	AHHHHHHHHHH
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3693' GR	Eddy.
16. Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
	REPORT OF:
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	PLUG AND ABANDONMENT
PULL OR ALTER CASING	
OTHER	
OTHER	
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1903. 	estimated date of starting any proposed
	estimated date of starting any proposed
work) see RULE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78.	
work) SEE RULE 1703. Spudded a 17 ¹ / ₂ " hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi	ng set at 414'.
TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w	ng set at 414'. /375 sacks Class "C"
TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi I-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv	ng set at 414'. /375 sacks Class "C" e strength at 70
TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi I-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not
<pre>work) SEE ROLE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. <u>TD 515'.</u> Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed
TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed
<pre>work) SEE ROLE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. <u>TD 515'.</u> Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed
work) SEE RULE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. <u>TD 515'</u> . Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12½", drilled plug and tested to 6 drilling.	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed
<pre>work) SEE ROLE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. <u>TD 515'</u>. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12½", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'.
<pre>work) SEE ROLE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. <u>TD 515'.</u> Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. <u>TD 2250'.</u> Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216',
<pre>work) SEE ROLE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco-
<pre>work) see RULE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks
<pre>work) see HoLE 103. Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12½", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to
<pre>work) SEE ROLE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate surface. WOC 18 hours, nippled up, pressure tested to 150</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to
<pre>work) see HoLE 103. Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12½", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to
<pre>work) SEE ROLE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate surface. WOC 18 hours, nippled up, pressure tested to 150</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to
<pre>work) SEE RULE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate surface. WOC 18 hours, nippled up, pressure tested to 150</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to
<pre>work) SEE RULE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate surface. WOC 18 hours, nippled up, pressure tested to 150 7-7/8", drilled plug and tested to 600#. OK. Resumed dri</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to
<pre>work) SEE RULE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate surface. WOC 18 hours, nippled up, pressure tested to 150 7-7/8", drilled plug and tested to 600#. OK. Resumed dri</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to
 work) SEE RULE 173. Spudded a 17½" hole at 11:00 PM 11-20-78. <u>TD 515'</u>. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. <u>TD 2250'</u>. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate surface. WOC 18 hours, nippled up, pressure tested to 150 7-7/8", drilled plug and tested to 600#. OK. Resumed dri 	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to 11ing.
<pre>work) SEE RULE 1703. Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate surface. WOC 18 hours, nippled up, pressure tested to 150 7-7/8", drilled plug and tested to 600#. OK. Resumed dri</pre>	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to 11ing.
 work) SEE RULE 173. Spudded a 17½" hole at 11:00 PM 11-20-78. <u>TD 515'</u>. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. <u>TD 2250'</u>. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate surface. WOC 18 hours, nippled up, pressure tested to 150 7-7/8", drilled plug and tested to 600#. OK. Resumed dri 18.1 horeby certify that the information above is true and complete to the best of my knowledge and bellef. 	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to 11ing.
Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12½", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate surface. WOC 18 hours, nippled up, pressure tested to 150 7-7/8", drilled plug and tested to 600#. OK. Resumed dri	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to 11ing.
 work) SEE RULE 173. Spudded a 17½" hole at 11:00 PM 11-20-78. <u>TD 515'</u>. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12¼", drilled plug and tested to 6 drilling. <u>TD 2250'</u>. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate surface. WOC 18 hours, nippled up, pressure tested to 150 7-7/8", drilled plug and tested to 600#. OK. Resumed dri 18. I hereby certify that the information above is true and complete to the best of my knowledge and bellef. 	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to 11ing.
 work) see Rule 1753. Spudded a 17½" hole at 11:00 PM 11-20-78. TD 515'. Ran 11 joints of 13-3/8" 48# K-55 (414') of casi 1-Guide shoe at 414' and insert float at 382'. Cemented w 4% CaCl. Slurry weight 14.8, 1.32 cu.ft/sack. Compressiv degrees, 1023 psi in 12 hours. PD at 1:30 PM 11-22-78. C circulate. WOC and filled hole w/5 yards of Ready-Mix. W off and reduced hole to 12½", drilled plug and tested to 6 drilling. TD 2250'. Ran 55 joints of 8-5/8" 24# K-55 (2256') of cas 1-guide shoe at 2250', insert float at 2216'. 1-centraliz centralizers and baskets at 1750, 945, & 745'. Cemented w Lite 6#/sack gilsonite, 1/4#/sack flocele, 2% CaCl. Follo Class "C" 2% CaCl. PD 3:00 PM 11-28-78. Cement circulate surface. WOC 18 hours, nippled up, pressure tested to 150 7-7/8", drilled plug and tested to 600#. OK. Resumed dri 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 	ng set at 414'. /375 sacks Class "C" e strength at 70 ement did not OC 12 hours, backed 00#. OK. Resumed ing set at 2250'. er at 2216', /850 sacks Howco- wed w/200 sacks d 20 sacks to 0#, reduced hole to 11ing.