

Submit 3 Copies  
to Appropriate  
District Office

**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

**P.O. Box 2088**

**Santa Fe, New Mexico 87504-2008**

**RECEIVED**

**FEB 15 1991**

**O. C. D.  
ARTESIA, OFFICE**

**WELL API NO.**

**30-015-22767**

**5. Indicate Type of Lease**

**STATE** ☒

**FED** ☐

**6. State Oil & Gas Lease No.**

**647-364**

**7. Lease Name or Unit Agreement Name**

**Empire Abo Unit "F"**

**8. Well No.**

**335**

**9. Pool Name or Wildcat**

**Empire Abo**

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS)

**1. Type of Well:**

**OIL  
WELL** ☒

**GAS  
WELL** ☐

**other**

**2. Name of Operator**

**ARCO OIL and GAS COMPANY**

**3. Address of Operator**

**P.O. Box 1610, Midland, Texas 79702**

**4. Well Location**

Unit Letter **E** : **2250** Feet From The **North** Line and **570** Feet from The **West** Line

Section **34**

Township **17S**

Range **28E**

**NMPM Eddy**

County

**10. Elevation (Show whether DF, RKB, RT, GR, etc.)**

**3664.3 GR**

**11. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

**PERFORM REMEDIAL WORK** ☐

**PLUG AND ABANDON** ☐

**TEMPORARILY ABANDON** ☐

**CHANGE PLANS** ☐

**PULL OR ALTER CASING** ☐

**(Other)** ☐

**SUBSEQUENT REPORT OF:**

**REMEDIAL WORK** ☐

**ALTERING CASING** ☐

**COMMENCE DRILLING OPNS.** ☐

**PLUG AND ABANDONMENT** ☐

**CASING TEST AND CEMENT JOB** ☐

**(Other) Recomplete Abo** ☒

**12. Describe Proposed or completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.**

**1-30-90. RUPU. POH w/CA. Set CIBP at 6170. Press test csg to 500#. Perf Abo f/6096-6110, 6134-6140. Acidize w/1500 gals. Swab test. Set CIBP at 6085. Perf Abo f/6065-6075. Swab test. RIH w/CA: 2 3/8 tbg & pkr set at 5965. RDPU 2-6-91.**

**2-08-90. In 24 hrs flowed 0 BO, 0 BW, 905 MCF 24/64 ck, 185# FTP.**

**13. I hereby certify that the information above is true and complete to the best of my knowledge and belief**

**SIGNATURE**

**Ken W. Gosnell**

**TITLE**

**Regulatory Coordinator**

**DATE**

**2/13/91**

**TYPE OR PRINT NAME**

**Ken W. Gosnell**

**TELEPHONE**

**(915) 688-5672**

**(This space for State Use)**

**ORIGINAL SIGNED BY**

**MIKE WILLIAMS**

**SUPERVISOR, DISTRICT II**

**APPROVED BY**

**TITLE**

**DATE**

**CONDITIONS FOR APPROVAL, IF ANY:**

**FEB 20 1991**