

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

APR 25 1991

WELL API NO. 30-015-22786
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "F"
8. Well No. 376
9. Pool name or Wildcat EMPIRE ABO
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3685.3' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator ARCO OIL AND GAS COMPANY ✓
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240	4. Well Location Unit Letter E : 1335 Feet From The NORTH Line and 700 Feet From The WEST Line Section 35 Township 17S Range 28E NMPM EDDY County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: TEMPORARILY ABANDON - <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN

TD - 6357'; PERFS: 5994-6002'

4-16-91 MIRU. DDP. ND WH NU BOP. UNSET PKR. PICKUP 4 JTS TBG. GIH TAG BOTTOM. POH w/TBG, S.N., AND PKR. RIH w/5-1/2" CIBP, RUNNING TOOL, AND TBG. SET CIBP POH w/1 JT TBG. PU KILL TRUCK. CIRCULATE WELL w/8.6# BRINE w/WT-675 CHEMICAL. CLOSE WELL IN. PRESSURE UP TO 500#. HELD FOR 15 MINS. POH w/TBG LAYING DOWN IN SINGLES. LEFT 1 JT ON WELLHEAD FLANGE. CIBP SET @ 5982.79'. PRESSURE TEST CHART ATTACHED. PRESSURE TEST WITNESSED BY DARREL MOORE, NMOC.

I hereby certify that the information shown is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Administrative Supervisor DATE 4/24/91

TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-1600

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 4/29/91

CONDITIONS OF APPROVAL, IF ANY:

