DIST. IBUTION	+			Supersedes Old
SANTA FE	1711	N MEXICO OIL	HE EVERIPIVC MANDSION	C-102 and C-103 Effective 1-1-65
FILE	TIV	R	EUEIVEB	· · · · · · · · · · · · · · · · · · ·
U.S.G.S.	+			Sa. Indicate Type of Lease
LAND OFFICE	+		JUN 28 1979	State Fee X
	+			5. State Oll 6 Gas Lease No.
DPERATOR				
(DO NOT USE THIS FO	SUNDRY APPLICATION	Y NOTICES AND REPORTS	UC BACK TO A DIFFERIAL RESERVOL	R. 7. Unit Agreement Norre
	. 🕅	OTHER-		8. Form or Lease Name
Name of Operator				Ingram Jackson BV
Yates Petrol	leum Co	rporation	· · · · · · · · · · · · · · · · · · ·	
Address of Operator				9. Well No.
207 South 4t	ch Stre	et - Artesia, NM.	88210	7
. Location of Well				10. Field and Pool, or Wildcat UT
UNIT LETTERG	1	.980 FEET FROM THE NOT	th 1980	FEET FROM E. Eagle Creek Atok
UNIT LETTER		FEET FROM THE	LINE AND	ALLEN TITTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT
East		26	17S 25E	
THE	LINE, SECTION	N TOWNSHIP	RANGE	HMPM. ())))))))))))))))))))))))))))))))))))
mmmm	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	15. Elevation (Show whet	ther DF RT CR etc. 1	12. County
MIMMMMM	111111	15. Elevation (Show Unel		Eddy
71111111111111	7777777	7//// 3368		
Ċ.	Check A	ppropriate Box To Indicate	e Nature of Notice, Repo	ort or Other Data
NOTI		TENTION TO:		SEQUENT REPORT OF:
			•	
PERFORM REMEDIAL WORK	٦	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	าี		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	รี	CHANGE PLANS	CASING TEST AND CEMENT JO	
	<u> </u>		OTHER Perforat	e and treat
		. r		
OTHER		L		
7. Describe Proposed or Co	ompleted Ope	erations (Clearly state all pertinent	details, and give pertinent dates	, including estimated date of starting any propos
work) SEE RULE 1103.				
TD 8430'; WI	LPBTD 8	3366' - WIH w/casir	ng gun on wirelin	e and perforated 8332-54
				46, 48, 54'. POH. WIH
w// .+1 no.		2-3/8"	tubing set nack	er at 8299'. Swabbed dry.
w/Gulberson		packer on 2-5/8	Cubing, set pack	ren u/hall goalong Subd
No shows. Th	ctd per	:f w/1000g 15% DS	30 acid and nitro	gen w/ball sealers. Swbd
no shows. Pu	ulled t	bg and pkr. Set CI	IBP at 8300' w/wi	reline. Dumped 1 bailer o
cmt on top	of pluc	1. PBTD 8288'. WIH	w/csg gun and pe	erf 8236-8245' (9') w/18 .
holes (2snf)) POH	RTH w/tho & Guibe	erson Uni VI pkr.	set pkr at 8205'. Trtd
	$\int \frac{1}{2} $	MS agid and nitro	gen w/ball sealer	s. Well cleaned up and fl
peris w/1500	JY 1/2/0	MB actu and netro	gen wybdre bedrei	d ponta w/0000g trtd flui
95# on 1/2"	choke	$= 6/6 \text{ MCF} (3 \text{ nr}_{*})$	rate). Sand Flac	d perfs w/9000g trtd flut
6000g MS fl	uid and	1 3000g CO-2, 1050	0# 20-40 sd. Swab	bed well dry. Blew well d
loaded thg.	unflar	nged, got off RBP,	instld BOP. Pull	ed tbg. WIH w/2-3/8" tbg
Cuibercon II	ni VT v	okr and RRP set R	BP at 8176', Pull	ed tbg. RIH w/Tub Conveye
Guiberson U		TTT when and when	\sim 00001 Dowfown	+od 8132_8130 + 1/28 50"
Gun, Guibers	son Uni	L VI pKr, set pKr a	at 8095 • Periora	ted 8132-8139' w/28 .50"
holes (4 sp:	f) No s	shows. Pulled guns	. WIH w/Guiberso	on Uni VI pkr on 2-3/8"the
set pkr at	8100'.	Trtd Perfs w/12000	g $7\frac{1}{2}$ % MS acid & N	Nitrogen w/ball sealers.
Well cleaned	d up au	nd flowed 110# on	1/2" choke = 770	MCFPD. Killed well & POOH
······································	d name	an WIH and latche	d on to bridge pl	Lug and reset at 8082'.
9. I hereby certify that the	information (above is true and complete to the be	est of my knowledge and belief.	(continued on accached]
\frown h	Л			
$(\cup \not) \rightarrow$		ml	Geol. Secty.	6-19-79
ISNED ALLA	<u>e</u>	ITIANIA TITLE		
	7	2 /		
1.1	A St	the second second	SUPERVISOR DISTRIC	JUN 2 9 1979

T11

ONDITIONS	OF	APPROVAL,	tF	ANY

Yates Petroleum Corporation Ingram Jackson BV No. 7 1980' FNL & 1980' FEL Section 26-175-25E Eddy County, New Mexico

(Continued from page 1)

WIH w/Casing Gun on Wireline and perforated 8030-8074' w/23 .50" holes as follows: 8030-38' (9 holes); 8046-48' (3 holes); 8041-44' (4 holes); 8068-74' (7 holes). WIH w/Guiberson Uni VI packer on 2-3/8" tbg, set packer at 7980' and treated perforations w/2000 gallons DS-30 acid and Nitrogen w/ball sealers. Well cleaned up and flowed 75# on 1/2" choke = 600 MCFPD. Pulled RBP at 8082' WIH w/Guiberson packer on 2-3/8" tubing, set packer at 8012' and Sand Frac'd all perforations 8030-8245' w/30000g gelled 3% acid and CO-2, 20000g gelled 3% acid; 10000g CO-2, 22500# 20-40 sand. Well cleaned up and flowed 260# on 24/64" choke = 910 MCFPD.