

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

RECEIVED

Form C-103  
Revised 1-1-89

CLSF  
Op

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL NO. **9-C-D**  
**30-015-22905**

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
**B-3818**

7. Lease Name or Unit Agreement Name  
**ur Spruck**

8. Well No.  
**5**

9. Pool name or Wildcat  
**Red Lake Queen Grbg. SA**

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
**Marbob Energy Corporation**

3. Address of Operator  
**P.O. Drawer 217, Artesia, NM 88210**

4. Well Location  
Unit Letter **F** : **2310** Feet From The **North** Line and **2310** Feet From The **West** Line  
Section **24** Township **17-S** Range **27-E** NMPM **Eddy** County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1) Spot 25 sacks cement plug at 2250' W.O.C. tag plug at 2002'  
2) Load hole W/mud  
3) Spot 40 sacks cement plug at 1600' tag plug at 1069'  
4) Spot 25 sacks cement plug at 900'  
5) Spot 25 sacks cement plug at 500'  
6) Spot 5 sacks cement plug at surface.

Part ID-2  
1-15-93  
P&A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Regina Maldonado* TITLE *Supervisor* DATE *12-28-92*

TYPE OR PRINT NAME \_\_\_\_\_ TELEPHONE NO. \_\_\_\_\_

(This space for State Use)

APPROVED BY *[Signature]* TITLE *[Signature]* DATE *4/20/94*

CONDITIONS OF APPROVAL, IF ANY: