

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	✓

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NOV 9 1979

O.C.C.

ARTESIA, OFFICE

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	5. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Summit Energy, Inc. ✓	5. State Oil & Gas Lease No.
3. Address of Operator 112 N. First Street, Artesia, New Mexico 88210	7. Unit Agreement Name
4. Location of Well UNIT LETTER F, 1800 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 16 S RANGE 25 E NMPM.	8. Farm or Lease Name Thigpen Et. A1.
15. Elevation (Show whether DF, RT, GR, etc.) 3526.8 GR	9. Well No. 1-Y
	10. Field and Pool, or Wildcat Wolfcamp Abc
	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Completion work <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up Well Service Unit on 8-1-79. Ran tubing, casing scrapper and bit. Cleaned out inside 5½" casing to 6690'. Perforated Atoka from 6588' - 6598' with 40 shots. Acidized with 2000 gals. acid. Treated 3 BPM at 2600 psi. Swabbed well dry. Very light show of gas. Ran wireline bridge plug and set at 5978'. Pressured up on plug to 3000 psi, for 30 minutes. Held o.k..

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rand White TITLE Vice President-Prod. DATE 11-8-79
APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE NOV 26 1979
CONDITIONS OF APPROVAL, IF ANY: