NO. OF COPIES RECEIVED	3	}	# N - #5%	Supersedes Old
DISTRIBUTION				C-102 and C-103
	17	NEW MEXICO OIL CONSE	RVATION COMMISSION	Effective 1-1-65
SANTA FE		1		
FILE	H-	-	061 78 18/3	5c. Indicate Type of Lease
u.s.g.s.	<del>  </del>	_		State X Fee
LAND OFFICE		4	D. C. C.	5. State Oil & Gas Lease No.
OPERATOR	<u> </u>	_	ARTESIA, OFFICE	647
				THITTHING THE
	SUND	RY NOTICES AND REPORTS ON !	WELLS	(1)
(DO NOT USE THIS FO	PR FOR PR	RY NOTICES AND REPORTS ON 100003ALS TO DRILL OR TO DEEPEN OR PLUG BATTON FOR PERMIT -" FORM C-1011 FOR SUCH	PROPOSALS.)	7. Unit Agreement Name
1.				7. Cini rigida
OIL GAS		OTHER-		8. Farm or Lease Name
Name of Operator ARC	7 21			1
PARTE		and Gus Compony	do 172 0	State BV
2. Address of Operator	Signario	entic Richneld Company A 4 C A	<del></del>	9. Well No.
	37 34			2
Box 1710, Hobbs,	New M	exico 88240		10. Field and Pool, or Wildcat
4. Location of Well			1770	Undesignated South
UNIT LETTER F		2109 FEET FROM THE North	LINE AND 1/8 FEET FROM	TITTE THE PERSON OF THE PERSON
r de la companya de		•		<i>XIIIIIIIIIIII</i>
_ West	LINE, SECT	TION 25 TOWNSHIP 17S	RANGE 28E NMPM	
THE				Trunch Hold Hallet
THITTING TO SEE	TITTI	15, Elevation (Show whether	DF, RT, GR, etc.)	12. County
	//////	2671.4' GR		_ Eddy
16.	77777	Appropriate Box To Indicate N	Sature of Notice Report of Ot	her Data
			SUBSPOLIEN	T REPORT OF:
NOT	ICE OF	INTENTION TO:	3003240211	
_	<u>.</u>	F-7		ALTERING CASING
PERFORM REMEDIAL WORK	_]	PLUG AND ASTANDON	REMEDIAL WORK	<u></u>
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT JOB X IN	rtermediate
POLE ON ALTON ONLINE			OTHER	
OTHER				in a data of starting any proposed
17. Describe Proposed or (	Completed	Operations (Clearly state all pertinent det	ails, and give pertinent dates, includin	g estimated date of starting any proposed
work) SEE RULE 1103	3.			
On 10/8/79 encou	untere	d water flow between 1339-	-1400' ARO 150 BPD, wat $\epsilon$	er flow increased @ 1/36'
ARO 4320 RPD 46	ecr to	1370 BPD. Finished drlg	12½" hole to 2650" @ 1:	30 AM 10/13/79. Kin W/
ARO 4320 BPD, decr to 1370 BPD. Finished drlg 12½" hole to 2650' @ 1:30 AM 10/13/79. RIH w/ 8-5/8" OD 28# S-80 csg, set @ 2650', FC @ 2567', ECP pkr @ 1634' & 1493', SC @ 1448'. Cmtd				
8-5/8" OD csg in 2 stages thru 2 3" lines from BH to control water flow. Cmtd 1st stage w/650				
sx C1 H RFC w/2# flocele/sk & 10# gilsonite/sk followed w/150 sx C1 C, 2% CaC1. Bumped plug &				
set both pkrs, water flow stopped. Cmtd 2nd stage w/700 sx C1 H RFC w/\frac{1}{2}\psi\$ flocele/sk, 10\psi\$				
set both pkrs, wa	ater 1.	10W Stopped. Gilled 21d 3te	2/70 Circ 162 ex cmt "	let stage & 225 sx cmt
gilsonite/sk. C.	losed	SC w/2000# @ 6:30 AM 10/13	Duese tested age to 150	10# 30 mine OK
2nd stage. WOC	36 hrs	. Drld out SC, FC & FS.	riess rested csg to 130	7011 JO MERIS OR
				•
18. I hereby certify that t	he informa	ition above is true and complete to the besi	t of my knowledge and belief.	
-				
PD.	1	0 TITLE	Dist. Drlg. Supt.	DATE 10/16/79
SIGNED_				
		1	SUPERVISOR, DISTRICT H	AAT 1 0 1070
1.	1/	Gress of	SUPERVISOR DISTRICT 44	OCT 1 8 1979