

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88218

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-015-23007

Indicate Type of Lease

STATE ☒

FEE

State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER Dry Hole

Name of Operator
BP America

Well No.

#42

Address of Operator

P.O. Box 1089 Eunice New Mexico 88231

Pool name or Wildcat

ABO

Well Location

Unit Letter F 2109 Feet From The North Line and 1778 Feet From The West Line

25 Section 17S Township 28E Range NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-7-02 MIRU

11-13-02 Tag Top of CIBP @ 5970'. Circulate Salt Gel Mud. Spot 25 sx on top of CIBP. Spot 25 sx 3720'. Spot 25 sx 2700'.

11-14-02 Tag Plug @ 2480'. Spot 60 sx @ 850' Covering shoe & yates @ 566'. Spot 15 sx 60'-Surface.

Cut off & install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE 11-14-02

TYPE OR PRINT NAME

TELEPHONE NO. 505-394.1600

(This space for State Use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

JAN 27 2003

DATE

xc: Rm M
01.06.03