

+ 50

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name  LEON ST.
8. Well No. 1
9. Pool name or Wildcat <i>Wildcat San Andres</i>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator GARRETT ENERGY INC.
3. Address of Operator P.O. BOX 866 - CARLSBAD, NEW MEXICO 88220
4. Well Location Unit Letter <u>A</u> : <u>66D</u> Feet From The <u>N</u> Line and <u>66D</u> Feet From The <u>E</u> Line Section <u>32</u> Township <u>16</u> Range <u>27</u> NMPM <u>EDDY</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3430.9' GL</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1. MOVE IN & RIG UP UNIT
- 2. SET 4½ CIBP AT 1720' AND CAP W/30' CEMENT
- 3. LOAD HOLE W/MUD
- 4. SPOT 25 SKS. CEMENT AT 1200'
- 5. 4½ CASING CEMENTED TO SURFACE, UNABLE TO PULL
- 6. SPOT CEMENT FROM 500' TO SURFACE TO COVER QUEENSE 10 3/4 SHOE.
- 7. SET UP P&A MARKER.

Post ID-2  
8-9-91  
P4A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado TITLE P&A SUPERVISOR DATE 7-24-91

TYPE OR PRINT NAME RAYMOND MALDONADO TELEPHONE NO. (505)397-3502

(This space for State Use)

APPROVED BY Johnny Robinson TITLE  DATE 8-26-91

CONDITIONS OF APPROVAL, IF ANY: