				Form C-103
N . OF CCPIES MECEIVED				Supersedes Old
DISTRIBUTION NEW MEXICO OIL CONSERV		UNTION PORTING COM	C-102 and C-103	
ANTAFE	NEW M	EXICO OIL CONSE	RAY HON-COWNISSION	Effective 1-1-65
-1LE /	1			5u. Indicate Type of Lease
J.S.G.S.			pg k ≤ 0 1 981	
AND OFFICE			F2 6 2 9 1301	
PERALOR	†			5, State Oil & Gas Lease No.
PERALOR	<u></u>		C. C. J.	
		DEBORTS ON I	MELLICATE NA CHIKE	
SUNDRY NOTICES AND REPORTS ON WELLSARIESTA, CONCE				
				7, Unit Agreement Name
				Bogle Farms
				8. Form or Leane Name
William N. Beach /				
				Bogle Farms
. Attress of genith				9, Well Do.
Box 3669, Midland, TX 79702				1
				15, Elela fra Fe a, er Wildedt
, Location of well	660	South	990	1 . (~
NIT CETTER		M THE	LINE AND FE	ET FR) N' CTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT
		16.6	20 F	
West	25	16-5	28-E	mer Allillillilli
19E	SECTION	TOWNSHIP	12100	
mmmmm	valid of VIIIII	ation (Show whether L	F, RT, GR, etc.)	12. Coasty
		3576 GR		Eddy ()))))
Ch	eck Appropriate Bo	x To Indicate Na	ature of Notice, Report	or Other Data
	OF INTENTION TO:	1	SUBSE	QUENT REPORT OF:
NO TEL	01 111 211 110 11			•
		JG AND ABANDON	REMEDIAL WORK	ALTERING CASING
DERPORM REMODEL WORK	PL	IG AND ABANDON	NEW COLOR	PLUG AND ABANCONMENT
PERFORANCE ABANCON			COMMENCE DRILLING OPNS.	
. OR ALTER CASING	CHA	ANGE PLANS	CASING TEST AND CEMENT JOB	
			OTHER	
C				
The street of the street Comple	etel Operations (Clearly s.	tute all pertinent deta	ils, and give pertinent dates, i	neluding estimated date of starting any propose
11 11/61 SEE RULE 1103.				
6-26-80 Ran GR/N	N log. TD 1625':	Perf 10 hole	s 15/5-99'; acidiz	e with 500 gal 15% NE and
ball seale	ers, swabbed bac	k acid. Well	swabbed dry.	
6-27-80 Fracture	e down casing wi	th 20,000 gal	gelled KCl water	& 29,000# sand.
6-27-80 Fracture down casing with 20,000 gal gelled KCl water & 29,000# sand. 6-28-80 Flow back treating water.				
6-29-80 Swab; got 100 bbls water with trace oil.				
6-29-80 Swab, got 100 bbis water with trace of .				
6-30-80 Swab bad	ck water			
7-1-80 Swab bad	ck water, swabbe	d dry.		
7-2-80 TP 240#. Died. Resume swabbing, swabbed dry. Re-acidize with 2000 gal NE.				
7-3-80 Swab. Water with trace oil				
7-4-80 TP 240#. Pumper tried to flow well, would not flow.				
7-4-80 IF 240#	. Tumper of red o	o rion nerry	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	·	7 / d		
12-19-80 Put on	pump. Made ∠ bb	is water/day.		
1-27-81 Set br	idge plug at 930	ı'. Perf 8 hol	es 862'-874'. Acid	ized with 2000 gal.
Swabbed d				
1-28-81 Fractured with 20,000 gal gelled water + 20,000# sand.				
1-29-81 Swab back water.				
1-30-81 Swab back water. 1-31-81 Put on pumpmaking 1 to 3 bbls water/day 1 hereby certify that the information above is true and complete to the best of my knowledge and belief.				
1-31-81 PUT On	pullip lilak Ing I	complete to the best	of my knowledge and belief.	
	/ 1			
ma 2 01	11.1/2	1	Clork	2-10-21
NENIO TITA ML	rupomel	V TITLE	UIEIK	2-19-81
	/ 			
	A 1.1			

CONDITIONS OF APPROVAL, IF ANY;

PATE FEB 2 4 1981