	·			
NO. OF COPIES RECEIVED		-		Form C-103
DISTRIBUTION			RECEIVED	Supersedes Old C-102 and C+103
SANTA FE	1_		NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	1	V		
U.S.G.S.			MAY 1 3 1980	5a. Indicate Type of Lease
LAND OFFICE				State X Fee
OPERATOR	1		O. C. D.	5. State Oil & Gas Lease No.
			ARTESIA, OFFICE	LG 5760
(DO NOT USE THIS FO	SU		Y NOTICES AND REPORTS ON WELLS posals to drill or to deepen or plug back to a different reservoir. Ion for permit	
1.				7. Unit Agreement Name
OIL GAS WELL WELL	L X		OTHER	
2. Name of Operator				8. Farm or Lease Name
Col	lora	ido	Interstate Gas Company	State
3. Address of Operator				9. Well No.
415	5 W.	8t	h, Amarillo, Tx. 79101	1
4. Location of Well				10. Field and Pool, or Wildcat
F		10	00 FEET FROM THE NOTTH LINE AND 2010 FEET FROM	Wildcat
UNIT LETTER	·			
West			ON 1 TOWNSHIP 16 <b>S</b> RANGE 28E NMPM.	
	.INE, 1	SECTI		
	$\Pi$	$\Pi$	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	111	$\prime \prime \prime \prime$	3553' G.L.	Eddy ())))))
16,	Che	s s s s	Appropriate Box To Indicate Nature of Notice, Report or Oth	Der Data
NOTI				REPORT OF:
NOTI				
PERFORM REMEDIAL WORK	7		PLUG AND ABANDON	ALTERING CASING
TEMPORARILY ABANDON	٦,		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	ī		CHANGE PLANS CASING TEST AND CEMENT JOB	
FULL ON ALIER CASING				· · · · · · · · · · · · · · · · · · ·
OTHER				<b></b>
VIAL8				

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Colorado Interstate Gas Company ran 51 joints of 8 5/8", 24# K-55 ST&C casing and set same at 1978' K.B. on May 4, 1980. The first stage was cemented with 350 sacks of class "H" with 2% Ca. Cl. First stage plug was bumped at 1:30 P.M. on May 4, 1980. After eight hours of circulation through the stage tool at 1585' the second stage was cemented with 3000 sacks of Class "H" with 10 lb./sacks salt and 10 lb/sacks # 20-40 sand and .6% CFR-2. After pumping 2500 sacks the well was shut in and the last 500 sacks were squeezed into formation starting at 1000 psig at 2 BPM to1750 psig at 2 BPM. The plug was bumped at 1950 psig. Second stage plug was bumped at 3:00 A.M. on May 5, 1980.

After 9 hours of W.O.C. the well was opened and nippled up. After 53.5 hrs. drilling operations were resumed. Cement was drilled to 1970; at this point the well was shut in and casing tested in accordance with Rule 107. Surface pressure of 750 psig was imposed. After 30 minutes the pressure was 720 psig indicating competent casing. The shoe was drilled and new formation cut to 2003'. The shoe and formation was then tested with 500 psig surface pressure (14.9 ppg equivalent) for 15 minutes. There was no leak off. A cement bond log was then run. While drilling the intermediate hole to 1994', several problems were encountered. An air pocket which unloaded the hole was encountered at approximately 978'. Pumping resumed and the well died. A severe salt water zone was encountered at 1553'. The well was shut in and 800 psig was recorded before the casing head developed a leak. Drilling was resumed and the zone continually flowed

(CONT'D SECOND PAGE) 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul D. Roberts	TITLE _ Petroleum Engineer	DATE 5/12/80
APPROVED BY W.a. Sesset	SUPERVISOR, DISTRICT. IL	MAY 1 4 1980
APPROVED BY MCC1, & Cash	TITLE	

CONDITIONS OF APPROVAL, IF ANY:

approximately 5 BPM until such time that the intermediate casing was cemented. The problem has now been alleviated.