M.O.G.D. **GOPY** DEPARTMENT OF THE INTERIOR (Other interior verse side)

instruction.

Form approved. ATE*

NM 1500/

		Budget	Burea	u N	o. 42-R	1424
5.	LEASE	DESIGN	ATION	AND	SERIAL	NO.
			~7			

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

GEOLOGICAL SURVEY						
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS	

(1% not use this form for proposals to drill or to deepen or plug back to a different reservoir.

If "APPLICATION FOR PERMIT" for such proposals.)

	후 10 10 10 10 10 10 10 10 10 10 10 10 10 	1	
].		7. UNIT AGREEMENT NAME	
WELL X WELL OTHER			
2. NAME OF OPERATOR		8. FARM OR LEASE NAME	
Forister & Sweatt 🕡	The Market of Market of the Control	Bear Draw	
3. ADDRESS OF OPERATOR	<u>C</u>	9. WELL NO.	
PO Box 161, Artesia, NM 88210		1	
4. LOCATION OF WELL (Report location clearly and in accordance with an See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT		
At surface	Wildcat / Bran Bran		
1980 FSI 660 FEL	11. SEC., T., E., M., OR BLK. AND C-G-SA		
		Sec 28 T16S R29E	

14. PERMIT NO.

Eddy

15. ELEVATIONS (Show whether DF. RT. GR. etc.) 3633.1 G.R.

12. COUNTY OR PARISH | 13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice. Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
	r : n		[į – į	<u></u>
TEST WATER SHUT-OFF		PULL OR ALTER CASING	į	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT		MULTIPLE COMPLETE	ļ	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE		ABANDON*		SHOOTING ON ACIDIZING	oil string casing
REPAIR WELL	1	CHANGE PLANS	· · · · · ·	(Other)	
(Other)				(Note: Report results of Completion or Recomplet	f multiple completion on Well

17. DESCRIBE PROPOSED OR COMPLETON OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and somes pertinent to this work.)*


Ran 8 jts. 326' 8 5/8" 20# 8 round Drilled $10\frac{1}{5}$ " hole to 329'. 1. ST & C casing set at 329'. Cemented with 100 sacks Class C with 2% Cal Ch. Plug down at 10:30 a.m. 4-26-81. Did not circulate. Finished filling hole with 2 yards ready mix to top of pipe.

Drilled 8" hole to 1745'. Ran 1745' 7" casing set at 1745' mudded. 5-22-81. With @ 1725 - 400-500' W/H 2.

Drilled $6\frac{1}{3}$ " hole to 2810'. Ran 69 jts. 2823' of $4\frac{1}{2}$ " 9.5# 8 round casing set at 2810'. 8-4-81. Pulled 1745' 7" casing. 8-5-81.

4.

Cemented 45" casing with 450 sacks Haliburton light with 6# salt 划 flocele and 150 sacks Class C 50/50 POz with 2% Gel 6# salt. Plug down 11:30 a.m. 8-6-81.



OIL & GAS U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct	et	
SIGNED (Theren Tours	- TUTLET BY ANGE	DATE 8/10/81
(This space for PAGECEFFE SED REFEE SORD ROGER A. CHAPMAN APPROVED BY	TIME 6	DATE
CONDITIONS OF APPROVAL, IF ANY:	111116	DATE

AUG 1 4 1901

U.S. GEOLOGICAL SURVEY See Instructions on Reverse Side

ROSWELL, NEW MEXICO